

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR17008774/KKA3Q2-1

Date: 09/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995141

Claimant
Vehicle No : SHD219X **Insured Vehicle No :** SLF7227T

Date of Loss: 02/05/2017 Nature of Claim: TP Claim No: 1182600236SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD219X	Engine No:	M9R8839C002582
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC281661
Reg. Date:	16/10/2015 (Man. Year: 2015)	Odometer:	70856 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Rovelo 3 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Rovelo 3 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,931.76	1,747.98	14,183.78	89.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,160.00	885.00	9,275.00	91.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	26,091.76	2,632.98	23,458.78	89.91
+ GST 7.00/7.00% (\$\$)	1,826.42	184.31	1,642.11	89.91
Nett Amount (\$\$)	27,918.18	2,817.29	25,100.89	89.91
+ Loss of Use (2.0 x S\$50.00/day) (\$\$)		100.00		
+ Car Rental (2.0 x S\$105.74/day) (\$\$)		211.48		
		(S\$)	3,128.77	
Liabile Amount (50.00%) (\$\$)		1,564.39		
+ Doc/Search Fee (\$\$)		6.00		
Nett Liability (\$\$)		1,570.39		
Global Sum Settlement (\$\$)		1,560.00		

INSPECTION

Date of Assignment: 03/05/2017

Date Inspected: 03/05/2017 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	968.78 FL	*968.78 FL
2	1		*BUMPER ABSORBER FRT	Serviceable	303.60 FL	*- FL
3	1		*BUMPER BEAM FRT	Repair	703.14 FL	*- FL
4	1		*BUMPER SPOILER FRT	Serviceable	139.81 FL	*- FL
5	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	159.40 FL	*- FL
6	1		*BUMPER RETAINER FRT LH	Distorted	116.47 FL	*116.47 FL
7	1		*BUMPER SUPPORT FRT LH (HEADLAMP LOWER)	Serviceable	18.37 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	363.71 FL	*- FL
9	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
10	1		*AIR CLEANER HOSE	Serviceable	58.57 FL	*- FL
11	1		*STEERING PUMP ELECTRIC	Serviceable	1,543.08 FL	*- FL
12	1		*BONNET	Repair	1,493.56 FL	*- FL
13	1		*RADIATOR GRILLE	Serviceable	1,313.68 FL	*- FL
14	1		*RADIATOR GRILLE BADGE RENAULT	Not Necessary	173.36 FL	*- FL
15	1		*RADIATOR GRILLE FRAME	Serviceable	1,041.35 FL	*- FL
16	1		*FRAME FULL SUPPORT PANEL	Serviceable	473.77 FL	*- FL
17	1		*HEADLAMP RH	Serviceable	911.10 FL	*- FL
18	1		*HEADLAMP LH	Serviceable	911.10 FL	*- FL
19	1		*HEADLAMP PANEL FRT LH	Repair	134.59 FL	*- FL
20	1		*FENDER PANEL FRT LH	Bent	602.95 FL	*602.95 FL
21	1		*FENDER PANEL FRT RH	Repair	602.95 FL	*- FL
22	1		*FENDER WHEELARCH FRT LH (LINNER)	Distorted	107.33 FL	*107.33 FL
23	1		*DOOR MIRROR LH	Serviceable	1,141.08 FL	*- FL
24	1		*DOOR FRT LH	Repair	2,188.20 FL	*- FL
25	1		*DOOR SEAL FRT LH	Serviceable	52.83 FL	*- FL
26	1		*ROCKER PANEL OUTER LH	Repair	759.61 FL	*- FL
27	1		*SET FRONT BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
28	1		*SET WHEELARCH CLIP LH	Necessary	66.00 FS	*66.00 FS
29	1		*TOW COVER FRT	Serviceable	14.50 FS	*- FS
30	1		*CAP HUB LH FRT	Serviceable	35.00 FS	*- FS
31	1		*RIM LH FRT	Serviceable	385.00 FS	*- FS
32	1		*TYRE LH FRT	Serviceable	330.00 FS	*- FS
33	1		*DOOR SEAL CLIP FRT LH	Not Necessary	4.68 FS	*- FS
34	1		*DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
35	1		*DOOR STICKER CLASSIC	Not Necessary	30.00 FS	*- FS
36	1		*SET BUMPER SUPPORT FRT CLIP LH	Not Necessary	9.80 FS	*- FS
37	1		*SET BUMPER RETAINER FRT CLIP LH	Not Necessary	12.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,587.13 1,927.53
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,655.37 179.55

Total Parts (\$\$) 15,931.76 1,747.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	4,200.00	400.00
2	TO CHECK ELETRICAL LIGHTING CONCERNED	New	170.00	15.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	440.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	TOWING FEES	New	120.00	0.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
9	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			10,160.00	885.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >