

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20007057/R1KA3Q2

**Date:** 16/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900079142

**Claimant**  
**Vehicle No :** SMJ9939B **Insured Vehicle No :** SKZ8066R

Date of Loss: 03/07/2020 Nature of Claim: TP Claim No: 4863489195SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMJ9939B</b>				
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI 7N24MY (A)		Engine No:	DED033910	
Reg. Date:	22/02/2019 (Man. Year: 2018)		Chassis No:	WVWZZZ7NZKV006997	
Colour:	Blue		Odometer:	13808 km	
Engine Capacity:	1984 cc				
Market Value/New Car Price:	N/A				
Sum Insured (S\$):	<b>Market Value/New Car Price</b>				

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,137.12	943.15	193.97	17.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	1,150.00	2,890.00	71.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,177.12</b>	<b>2,093.15</b>	<b>3,083.97</b>	<b>59.57</b>
<b>+ GST 7.00/7.00% (S\$)</b>	362.40	146.52	215.88	59.57
<b>Nett Amount (S\$)</b>	<b>5,539.52</b>	<b>2,239.67</b>	<b>3,299.85</b>	<b>59.57</b>
<b>+ Car Rental (2.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		256.80		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,498.47</b>		

### INSPECTION

Date of Assignment: 09/07/2020

Date Inspected: 09/07/2020 Inspected At:

VOLKSWAGEN GROUP  
SINGAPORE PTE LTD  
247 Alexandra Road  
Singapore 159934

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD RASUL

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR VIEW MIRROR HOUSING	Scratched	815.28 FS	*815.28 FS
2	1		*MIRROR CAP PRIMED RHF	Cracked	127.87 FS	*127.87 FS
3	1		*MIRROR GLASS RHF	Serviceable	184.69 FS	* - FS
4	4		*FILLISTER HD SCREW WITH	Not Necessary	9.28 FS	* - FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>1,137.12</b>	<b>943.15</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
3	LABOUR	New	1,680.00	420.00
4	SPRAY PAINTING	New	1,600.00	250.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,040.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >