

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20007058/ADS3Q2

Date: 26/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100481453

Claimant
Vehicle No : SLN587H **Insured Vehicle No :** SLF6857G

Date of Loss: 06/07/2020 Nature of Claim: TP Claim No: 6024533008SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN587H	Engine No:	CVN033179
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF45HA126031
Reg. Date:	20/04/2017 (Man. Year: 2017)	Odometer:	30265 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,097.00	8,574.40	6,522.60	43.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,992.00	2,542.00	3,450.00	57.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,089.00	11,116.40	9,972.60	47.29
+ GST 7.00/7.00% (S\$)	1,476.23	778.15	698.08	47.29
Nett Amount (S\$)	22,565.23	11,894.55	10,670.68	47.29
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,136.55		

INSPECTION

Date of Assignment: 08/07/2020

Date Inspected: 08/07/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,010.00 FS	*1,608.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	269.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	67.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	185.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	198.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Cracked	59.00 FS	*47.12 FS
7	1		*RADIATOR GRILLE	Not Necessary	1,084.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	127.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	757.00 FS	*- FS
10	1		*FRONT BUMPER GUIDE SECTION - RH	Cracked	36.00 FS	*28.16 FS
11	1		*FRONT BUMPER COVER	Not Necessary	120.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	117.00 FS	*- FS
13	1		*LOCK CARRIER BRACKET	Not Necessary	129.00 FS	*- FS
14	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Not Necessary	54.00 FS	*- FS
15	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
16	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
17	1		*HORN - RH LOW TONE	Not Necessary	119.00 FS	*- FS
18	1		*SPRING SHACKLE - RH	Not Necessary	27.00 FS	*- FS
19	1		*FRONT FENDER - RH	Dented	722.00 FS	*577.60 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
21	1		*FRONT FENDER CLOSING ELEMENT - RH	Damaged	47.00 FS	*37.28 FS
22	1		*FRONT FENDER BRACKET - RH FRONT	Not Necessary	33.00 FS	*- FS
23	1		*DEFORMATION ELEMENT BRACKET - RH REAR	Not Necessary	46.00 FS	*- FS
24	1		*FRONT FENDER BRACKET - RH FRONT	Not Necessary	30.00 FS	*- FS
25	1		*FRONT FENDER BRACE - RH	Bent	112.00 FS	*89.20 FS
26	1		*WHEEL HOUSING LINER - RH	Torn	228.00 FS	*182.00 FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	86.00 FS	*- FS
28	1		*WHEEL SPOILER	Torn	69.00 FS	*55.04 FS
29	1		*WHEEL SPOILER TRIM	Not Necessary	34.00 FS	*- FS
30	1		*STONE CHIP GUARD	Necessary	48.00 FS	*37.92 FS
31	1		*FENDER LEDGE COVER - UPPER	Necessary	29.00 FS	*23.20 FS
32	1		*FENDER LEDGE COVER - LOWER	Necessary	21.00 FS	*16.72 FS
33	1		*LED HEADLIGHT - RH	Cut	7,321.00 FS	*5,856.80 FS
34	1		*LIFT CYLINDER - RH		198.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
35	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	88.00 FS	*- FS
36	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	18.00 FS	*- FS
37	1		*RADIATOR AIR GUIDE - RH	Not Necessary	27.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE - RH	Not Necessary	12.00 FS	*- FS
39	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
40	1		*SUNDRIES	Necessary	300.00 FS	*15.36 FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	15,097.00	8,574.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNITS AND POWER MODULES. TO CARRY OUT CALIBRATION	New	350.00	250.00
2	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS FRONT FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER AND RHS FRONT DOOR	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,992.00	2,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >