


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB279Z  
 Ref. No : BUS/01/16/7025  
 Reg. Date : 01/01/1900  
 Vehicle Type : BUS -12M  
 Make : MAN  
 Model : MAN  
 Name of Driver : Isparan A/L G Munusamy  
 Type of Accident : HEAD TO SIDE  
 Date / Time of Accident : 20/01/2016 05:27:00 PM  
 Accident Reported Date / Time : 21/01/2016 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : China Tai Ping  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC,if any :  
 FRONT LEFT PORTION.  
 TP'S VEH: GQ9234K  
 Prepared Date : 21/01/2016 06:20:12 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No :

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 795.00	530.00
Total Spray Painting Charges	: 446.00	300.00
Total Material Charges	: 687.74	701.78
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 1,928.74</b>	<b>1,531.78</b>
<b>Lum Sum Total</b>	<b>: 1,950.00</b>	<b>1,550.00</b>
No. of Repair Days	: 3.00	2.00
Prepared / Adjusted By	:	kalvin (LKK)
Arc / Surveyor Sign Off Date	: 01/03/2017 10:57:29 AM	01/03/2017 10:59:26 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/03/2017 10:57:29 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :


Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :



## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	795.00	530.00
<b>Total Labour</b>	<b>795.00</b>	<b>530.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	446.00	300.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>446.00</b>	<b>300.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
F01001-CW264		6010153	FRONT HEADLAMP PANEL LH	1	974.70	10.00	877.23	Replace	Replace	No
<b>TOTAL MATERIALS</b>								<b>877.23</b>	<b>877.23</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>687.74</b>	<b>701.78</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									