

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: XD5618E200623

Estimate**Customer**

Name: China Taiping Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Date: 13-07-20

Vehicle No: XD5618E

Model/Make: Hino SH1EERA

13L Manual ABS Turbo

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Door <i>3650</i> <i>Sub 500</i>	\$ 5,639.70	
2	Front Rh Door "2041" Emblem <i>rec</i> <i>(102)</i>	\$ 145.00	
	To check all wiring & electrical component for proper function <i>11</i>	\$ 30.00	X
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 50.00	- 30
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	- 400
	To putty & spray painting & including touch up paint on accident affected	\$ 500.00	- 350

Total Parts & Labour of estimate for damaged vehicle

\$6,964.70

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

Not Authorized
Wah
1/5 \$3300
4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

*P- 3798**102**P-341550**L-780.00**4195-50**203**3356*