Adjuster Report Page 1 of 5

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## **VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CS/III20007068/AVF3E2

N/A

**Date:** 24/07/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle SCU8278S

Insured Vehicle No: SMA1634E

No:

Date of Loss: 06/07/2020 Nature of Claim: TP Claim No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SCU8278S

 Make & Model:
 BMW 528I, 2.0 (A)
 Engine No:
 B2090365N20B20A

 Req. Date:
 21/12/2012 (Man. Year: 2012)
 Chassis No:
 WBAXG32060D121646

Colour: Silver Odometer: 114383 km

Engine Capacity: 1997 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 245/40 R19 Rear Tyre Size: 245/40 R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,904.00	11,122.90	12,781.10	53.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,780.00	3,160.00	1,620.00	33.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,684.00	14,282.90	14,401.10	50.21
Approved Total (Overridden) (S\$)		11,400.00		
Nett Amount (S\$)	28.684.00	11.400.00	17.284.00	60.26

INSPECTION

Date of Assignment: 07/07/2020

Date Inspected: 07/07/2020 Inspected At: Jec Automotive (HQ)

1 KAKI BUKIT AVENUE 6, #02-11

AUTOBAY

Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 5 Adjuster Report

# **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jul 2020)

Parts: 143 BMW 528I 2.0 (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SCU8278S)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cut	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER	Torn	1,546.00 F	*1,546.00 FL
4	1		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	192.00 F	*- FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	35.00 F	*- FL
7	4		*FRONT BUMPER SENSOR	Not Necessary	1,040.00 F	*- FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	105.00 F	*- FL
9	1		*FRONT BUMPER LOGO	Necessary	68.00 F	*68.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	645.00 F	*-FL
11	2		*FRONT GRILLE	Cracked	310.00 F	*310.00 FL
12	2		*HEADLAMP	Not Necessary	5,734.00 F	*-FL
13	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*-FS
14	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*-FS
15	1		*REAR BUMPER	Distorted	1,563.00 F	*1,563.00 FL
16	1		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
17	2		*REAR BUMPER SIDE GUIDE	Cracked	282.00 F	*282.00 FL
18	1		*REAR BUMPER TOW COVER	Not Necessary	68.00 F	*- FL
19	2		*REAR BUMPER REFLECTOR	Cracked	118.00 F	*118.00 FL
20	1		*REAR BUMPER REINFORCEMENT	Dented	691.00 F	*691.00 FL
21	1		*REAR BUMPER LOWER GARNISH	Deformed	310.00 F	*310.00 FL
22	1		*REAR BUMPER UNDERCOVER	Missing	76.00 F	*76.00 FL
23	1		*REAR BUMPER UNDERCOVER CLIPS	Necessary	20.00 F	*20.00 FL
24	1		*REAR BUMPER REINFORCEMENT COVER	Cracked	98.00 F	*98.00 FL
25	1		*REAR BUMPER KICK SENSOR	Not Necessary	405.00 F	*-FL
26	1		*REAR BUMPER KICK SENSOR COVER	Cracked	142.00 F	*142.00 FL
27	1		*REAR BUMPER INNER FRAME COVER	Cracked	201.00 F	*201.00 FL
28	1		*REAR END PANEL	Dented	885.00 F	*885.00 FL
29	1		*REAR END PANEL TOP GARNISH	Cracked	162.00 F	*162.00 FL
30	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
31	2		*TAILLAMP	Cracked	1,336.00 F	*1,336.00 FL
32	2		*TAILLAMP PANEL	Repair	590.00 F	*- FL
33	1		*BOOTLID	Dented	1,602.00 F	*1,602.00 FL
34	1		*BOOTLID LOCK	Damaged	425.00 F	*425.00 FL
35	1		*BOOTLID WEATHERSTRIPE	Necessary	299.00 F	*299.00 FL
36	1		*BOOTLID REFLECTOR	N/S Cracked	716.00 F	*358.00 FL
37	1		*BMW LOGO	Necessary	58.00 F	*58.00 FL
38	1		*528I EMBLEM	Necessary	62.00 F	*62.00 FL
39	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	332.00 F	*-FL

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_... 24/7/2020

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars		Condition	Repairer's	Amount
40	1		*REAR EXHAUST PIPE		Repair	1,423.00 F	*- FL
41	2		*REAR EXHAUST TAIL	. PIPE	Bent	340.00 F	*340.00 FL
42	1		*REAR CAMERA		Not Necessary	685.00 F	*- FL
43	1		*REVERSE SENSOR (4PCS)		Damaged (2Pcs Only)	1,060.00 F	*530.00 FL
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.				
					Sub Total (S\$)	23,904.00	11,702.00
- List Item Discount on L Items 0.00/5.00% (S\$)			0.00	579.10			
					Total Parts (S\$)	23,904.00	11,122.90
			Rep	ort was unsubmitted durin	g this print-out.		

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,800.00	1,200.00
2	SPRAY PAINTING	New	1,600.00	1,200.00
3	WIRING	New	150.00	60.00
4	TO REMOVE FRONT BUMPER SENSORS	New	150.00	80.00
5	TO UNDERSEAL	New	150.00	80.00
6	TO REMOVE REVERSE SENSOR	New	150.00	80.00
7	TO REMOVE REAR CAMERA	New	100.00	60.00
8	TO REMOVE UPHOLSTERY	New	180.00	80.00
9	TO REMOVE EXHAUST PIPE	New	150.00	120.00
10	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
11	TO PERFORM DIAGNOSTIC TEST	New	200.00	120.00
		Gross Labour Cost (S\$)	4,780.00	3,160.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.