

SCU8278S.
BMW 528i
WBA X 632060D121646.

TP III
Veron.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: 30(SN) ✓

Signature:

Date:

30(SN) ✓

Front Number Plate *nt*
Front Number Plate Holder *deland*
Front Bumper *ton*
Front Bumper Clips *new*
Front Bumper Side Holder x 02 *nt new*
Front Bumper Tow Cover *nt new*
Front Bumper Sensor x 04 *nt new*
Front Bumper Lower Grille *nt new*
Front Bumper Logo *new*
Front Bumper Reinforcement *nt new*
Front Grille x 02 *cracked*
Headlamp x 02 *nt new*

1546 ✓

50 ✓

96x2 = 192 x

35 x

260x4 = 1040 x

105 x

68 ✓

645 x

155x1 = 310 ✓

2867x2 = 5734. x

Rear Number Plate *2 new*
Rear Number Plate Holder *new*
Rear Bumper *Distorted*
Rear Bumper Clips *new*
Rear Bumper Side Guide x 02 *cracked*
Rear Bumper Tow Cover *nt new*
Rear Bumper Reflector x 02 *cracked*
Rear Bumper Reinforcement *Distorted*
Rear Bumper Lower Garnish *deland*
Rear Bumper Undercover *Missing*
Rear Bumper Undercover Clips *new*
Rear Bumper Reinforcement Cover *cracked*
Rear Bumper Kick Sensor *nt new*

30(SN) x

30(SN) x

1563 ✓

50 ✓

141x2 = 282 ✓

68 x

59x2 = 118 ✓

691 ✓

310 ✓

76 ✓

20 ✓

98 ✓

405 x

ABC

SCU8278S.

Rear Bumper Kick Sensor Covers	Cranked	142	✓
Rear Bumper Inner Frame Covers.	Cranked	201	✓
Rear End Panel	Dented	885	✓
Rear End Panel Top Garnish.	Cranked	162	✓
Rear End Panel Sealant.	None	60(SN)	✓
Taillamp x 02	Cranked	668x2 = 1336	✓
Taillamp Panel x 02	Repair	295x2 = 590	+
Bootlid	Dented	1602	✓
Bootlid Lock	Damaged	425	✓
Bootlid Weatherstripe	re	299	✓
Bootlid Reflector x 02	LH Cracked	358x2 = 716	358

~~Bootlid Dumper x 02~~

BMW Logo	2 None	58	✓
528i Emblem.	1 None	62	✓
Spare Tyre Panel Top Cover	None	332	+
Rear Exhaust Pipe	Repair	1423	+
Rear Exhaust Tail Pipe x 02	Best	170x2 = 340	✓
Rear Camera	None	685	+

List 11582 Reverse Sensor x 04 2 pieces damaged 265x4 = 1060 530

LWS 5%: 11002-90

SN: 120 Panel Beating	1800	1200
Labour: 3160 Spray Painting.	1600	1200
Total: 1922 90 Wiring	150	60.
L/S: 11.4K. To remove front bumper Sensors.	150	80.
10 Days. To underseal.	150	80
To remove reverse sensor	150	80
To remove rear camera.	100	60
To remove upholstery.	180	80
To remove exhaust pipe	150	120
To transfer bootlid fittings.	150	80
To perform diagnostic test	200	120

ABC

\$28,684.00