

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2102733

3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV Date 19/04/2021

Reference CC6/CTI20007072/Kpa3q2

Code CTI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SML 2665B

Insured Veh. GBH 7720T

Claim No. SNM20D202355

Policy No. DMCVSN1830111901

Accident Date 03/07/2020

Inspection Date 07/07/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile				
	CHINA TAIPING INSURANCE (S) PTE LTD Ref: CC6/CTI20007072/Kpa3q2				
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 WERSINGAPORE 079909	Date:	19/04/2021	
			Code	СТІ	
1.	Policy Particulars :- THIRD PARTY CLAIM			M	
	Insured Veh.	GBH 7720T	Veh. Inspected	SML 2665B	
	Policy No.	DMCVSN1830111901	Coverage (\$)	0.00	
	Claim No.	SNM20D202355	Excess (\$)	0.00	
	Assign From		Assign Date	07/07/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA VOXY (A)	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	Chassis No. ZWR800350488 Colour		METALLIC DARK BLUE	
	Odometer	128086 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	DUNWING	8 mm	
	L/H Front Tyre	195/65 R15	DUNWING	8 mm	
	R/H Rear Tyre	195/65 R15	DUNWING	8 mm	
	L/H Rear Tyre	195/65 R15	DUNWING	8 mm	
4.		Description	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	REAR BODY.		
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	03/07/2020	Inspection Date	07/07/2020	
	Survey held at	OPTIMA WERKZ PTE LTD			
		9A SERANGOON NORTH AVE SINGAPORE 554500	5		
5a.		Re	emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W			
5b.		Estimate Days of Repair			
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	7 Wor	king Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 2665B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / CUT	861.70	861.70
10	REAR BUMPER CLIPS @\$5.80	NECESSARY	58.00	58.00
1	REAR BUMPER SIDE BRACKET LH	CRACKED	75.30	75.30
1	REAR TAIL LAMP LOWER GARNISH COVER LH	TO REPAIR SEE LABOUR	196.50	-
1	REAR TAIL LAMP LOWER GARNISH COVER BRACKET LH	SERVICEABLE	170.20	-
1	REAR FENDER QUARTER PANEL LH	BENT	1,595.40	1,339.10
1	REAR SLIDING DOOR LH	BENT	1,817.60	1,817.60
12	REAR SLIDING DOOR INNER TRIM CLIPS LH @\$5.50	NOT NECESSARY	17.50	-
	LESS 25% DISCOUNT		-1,198.05	-1,037.93
			3,594.15	3,113.77
	SPECIAL NETT ITEMS			
1	REAR SIDE GLASS SEALANT LH (SN)	NECESSARY	80.00	40.00
			80.00	40.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP LOWER GARNISH COVER LH.		1,200.00	750.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER,REAR TAIL LAMP GARNISH COVER LH,REAR FENDER QUARTER PANEL LH,REAR SLIDING DOOR LH,FUEL FILLER LID PANEL & ETC.		1,000.00	800.00
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR SLIDING DOOR LH INNER MECHANISM & ETC.TO REFFECT REPLACE OF REAR SLIDING DOOR LH.		120.00	60.00
	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR.TO EFFECT REPLACE OF REAR BUMPER.		80.00	50.00
	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		60.00	20.00
	LABOUR CHARGES TO REMOVE & REFIX,REPLACE REAR QUARTER PANEL SIDE GLASS LH,SIDE GLASS SEALANT LH & ETC.TO EFFECT REPLACE OF REAR QUARTER PANEL LH.		120.00	80.00

Report Ref No. CC6/CTI20007072/Kpa3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REFIX FUEL FILLER PIPE & ETC.TO EFFECT REPLACE OF REAR QUARTER PANEL LH.		80.00	60.00
			2,660.00	1,820.00
	GRAND TOTAL		6,334.15	4,973.77

RECOMMENDED COST OF LUMP SUM REPAIRS		3,950.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI20007072/Kpa3q2

KONG SENG CHEONG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SML 2665B

#### **INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SML 2665B

**RE-INSPECTION** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SML 2665B

**RE-INSPECTION** 



