

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 154/2017/js Date: 23th December 2020

Our Ref: CS1/LAW20007077/Atf3e2

M/s Joseph Gay & Company

151 Chin Swee Road #02-16 Manhattan House Singapore 169876

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLH 5820H

INSURED VEHICLE: JPX 4074 ACCIDENT DATE: 12/04/2017

We thank you for your instruction on 06/07/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLH 5820H from M/s Hui Yang Motor Pte Ltd.
- b) Final Repair Bill of SLH 5820H from M/s Hui Yang Motor Pte Ltd.
- c) Singapore Accident Statement of Vehicles SLH 5820H.
- d) Police Report of Vehicles SJM 7710B and SLH 5820H and JPX 4074.
- e) Colour damaged vehicle photographs of SLH 5820H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLH 5820H

Make & Model : Toyota Vellfire, 2.4 Z G-Edition

Chassis Number : ANH208230349

Year of Registration : 2012

- 2. We recommend that the repairs of the entire damage require about <u>18 (Eighteen)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.