

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007079/URA3Q2

Date: 16/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMQ8591P

Insured Vehicle No : SLA6020E

Date of Loss: 06/07/2020

Nature of Claim: TP

Claim No: 5275731333SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMQ8591P

Make & Model: HONDA FIT, 1.3 GF CVT (A)

Engine No: L13B1450855

Reg. Date: 06/12/2019 (Man. Year: 2018)

Chassis No: GK31342709

Colour: Black

Odometer: 4491 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,386.50	1,105.95	1,280.55	53.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,350.00	700.00	34.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,436.50	2,455.95	1,980.55	44.64
+ GST 7.00/7.00% (S\$)	310.56	171.92	138.64	44.64
Nett Amount (S\$)	4,747.06	2,627.87	2,119.19	44.64
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,029.87		

INSPECTION

Date of Assignment: 03/08/2020

Date Inspected: 03/08/2020 Inspected At:

HOCK WAH MOTOR WORKSHOP PTE LTD

3011 BEDOK INDUSTRIAL PARK E

#01-2008

SINGAPORE 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (WCP)	Badly Dented	420.00 F	*420.00 F
2	1		*TAILGATE EMBLEM (WCP)	Not Necessary	18.00 F	*- F
3	1		*TAILGATE LOGO -FIT (WCP)	Necessary	18.00 F	*18.00 F
4	1		*TAILGATE TRIMBOARD (WCP)	Not Necessary	55.00 F	*- F
5	1		*TAILLAMP RH (WCP)	Not Necessary	200.00 F	*- F
6	1		*END PANEL (WCP)	Repair	230.00 F	*- F
7	1		*END PANEL TOP GARNISH (WCP)	Not Necessary	40.00 F	*- F
8	1		*REAR FENDER INNER TRIMBOARD RH (WCP)	Not Necessary	150.00 F	*- F
9	1		*REAR BUMPER (WCP)	Dented	200.00 F	*200.00 F
10	1		*REAR BUMPER RETAINER RH (WCP)	Not Necessary	12.00 F	*- F
11	1		*REAR BUMPER RETAINER LH (WCP)	Not Necessary	12.00 F	*- F
12	1		*REAR BUMPER LOWER CENTER SPOILER (WCP)	Cracked	45.00 F	*45.00 F
13	1		*TAILGATE WINDSCREEN MOULDING (WCP)	Necessary	70.00 F	*70.00 F
14	1		*TAILGATE OUTER GARNISH (WCP)	Not Necessary	130.00 F	*- F
15	1		*REAR REFLECTOR LAMP RH (WCP)	Not Necessary	70.00 F	*- F
16	1		*TAILGATE LOCK (WCP)	Not Necessary	75.00 F	*- F
17	1		*TAILGATE RUBBER (WCP)	Not Necessary	45.00 F	*- F
18	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
19	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
20	1		*REAR FENDER RH (NPA)	Not Necessary	0.00 FS	*- FS
21	1		*SPARE TYRE PANEL (NPA)	Not Necessary	0.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,118.00	993.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	268.50	112.95
Total Parts (\$\$)	2,386.50	1,105.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	550.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	600.00
3	ANTI-RUST COATING	New	120.00	30.00
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (S\$)			2,050.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >