

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17000333/M1TBE2
Date: 31/05/2017

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100454516		
Claimant Vehicle No :	GX3476G	Insured Vehicle No :	SLA3809S		
Date of Loss:	31/12/2016	Nature of Claim:	TP	Claim No:	8528266917SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX3476G		
Make & Model:	PEUGEOT PARTNER, 1.6 D (M)	Engine No:	HIDDEN
Reg. Date:	01/04/2004 (Man. Year: 2004)	Chassis No:	VF3GCWJYB96070980
Colour:	Black	Odometer:	401879 km
Engine Capacity:	1868 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R14	Rear Tyre Size:	185/60 R14
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/01/2017		
Date Inspected:	09/01/2017	Inspected At:	Kum Chew Motor Workshop (HQ) 12 Sin Ming Industrial Estate, #01-71 Singapore 575656
Estimated Period of Repair:	5.0 days		

Adjuster: MA CHIN FOOK

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Dented	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F
3	1		*FRT BUMPER	Dented	0.00 F	*- F
4	1		*FRT BUMPER LOWER GRILLE	Cracked	0.00 F	*- F
5	1		*FRT BUMPER REINFORCEMENT	Broken	0.00 F	*- F
6	1		*FRT LOWER PANEL	Dented	0.00 F	*- F
7	1		*AIR CON CONDENSER	Dented	0.00 F	*- F
8	1		*AIR CON LIQUID PIPE	Bent	0.00 F	*- F
9	1		*RADIATOR	Dented	0.00 F	*- F
10	1		*RADIATOR COWLING	Cracked	0.00 F	*- F
11	1		*RADIATOR FAN ASSY	Damaged	0.00 F	*- F
12	1		*AIR DUCT	Cracked	0.00 F	*- F
13	1		*COMPRESSOR	Cut	0.00 F	*- F
14	1		*ALTERNATOR	*Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

LKK Auto Consultants Pte Ltd/GX3476G/31/05/2017 09:56

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/GX3476G/31/05/2017 09:56

< END OF ESTIMATES >