



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 3476G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	780.00	650.00
8	FRONT BUMPER CLIP	NECESSARY	26.00	26.00
1	FRONT BUMPER REINFORCEMENT	DENTED	288.00	288.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	168.00	168.00
1	FRONT GRILLE	SERVICEABLE	468.00	-
1	FRONT GRILLE EMBLEM	SERVICEABLE	55.00	-
4	FRONT GRILLE CLIP	NECESSARY	25.00	25.00
1	R/H HEADLAMP	SERVICEABLE	418.00	-
1	AIRCON CONDENSER	DENTED	770.00	770.00
1	AIRCON PRESSURE PIPE	SERVICEABLE	168.00	-
1	AIRCON SUCTION PIPE	DENTED	165.00	165.00
1	RADIATOR ASSY	CRUMPLED	740.00	740.00
1	RADIATOR FAN	SERVICEABLE	420.00	-
1	RADIATOR FAN COWLING	CRACKED	265.00	265.00
1	AIR FILTER HOSE	SERVICEABLE	102.00	-
1	POWERING STEERING COOLING PIPE	SERVICEABLE	178.00	-
1	ALTERNATOR	CRUMPLED	1,055.00	920.00
1	AIRCON COMPRESSOR	CRUMPLED	1,182.00	980.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	650.00	-
1	R/H FRONT SUPPORT PANEL DUST COVER	CRACKED	45.00	45.00
1	L/H FRONT SUPPORT PANEL DUST COVER	CRACKED	45.00	45.00
1	FRONT LOWER CROSS MEMBER PANEL	DENTED	465.00	465.00
	LESS 10% DISCOUNT		-	-555.20
			8,478.00	4,996.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DENTED	50.00	40.00
			50.00	40.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,200.00	400.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		850.00	300.00
	TO REMOVE / RENEW AIRCON CONDENSER & REFILL GAS.		180.00	100.00
	TO REMOVE / RENEW RADIATOR ASSY.		180.00	60.00
	TO CHECK WIRING FUNCTIONS.		250.00	20.00
			2,660.00	880.00
	GRAND TOTAL		11,188.00	5,916.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,750.00

Report Ref No. CS3/AIG17000333/Qtf3e2-1

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.