

PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L

Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref : PS/005/01/17

Date : 22nd July 2019

Mr Foo Jong Peng
c/o 160 Sin Ming Drive
#05-08 Sin Ming Auto City
Singapore 575722

Dear Sir,

Re : **THIRD PARTY CLAIM**

We refer to your instruction to appraise the vehicle **GX 3476 G** on 12th January 2017.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Kum Chew Motor Workshop** for **\$11,188.00** as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of **\$6,700.00 lump sum** corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **FIVE (5) days**. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES


LOUIS S C NG CAE AMIMI
Dip. MTM. Automotive Engineer
Licensed Appraiser

Encl.

PRESTIGE APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: Mr Foo Jong Peng
c/o 160 Sin Ming Drive
#05-08 Sin Ming Auto City
Singapore 575722

Date : 22nd July 2019
Our Ref : PS/005/01/17
Policy No :
Sum Insured :
Excess : T/P Claim

Assigned By : Mr Foo Jong Peng
Assignment Date : 12th January 2017
Accident Date : 31st December 2016
Inspection Date : 12th January 2017
Workshop Name : Kum Chew Motor Workshop
Survey Conducted At : Sin Ming Carpark

PARTICULARS OF VEHICLE

Registration No	: GX 3476 G	Mileage	: -
Make/Model	: Peugeot Partner	Engine No	: HIDDEN
Type Of Body	: Van	Chassis No	: VF3GCWJYB9607980
Year Of Manu./Regn.	: 2004	Passenger Cap.	: 1 Passenger
Colour	: Black	Others	: -

CONDITION OF TYRES

R/H SIDE

Front Tyre : 4mm 175/65R14 Continental
Rear Tyre : 4mm 175/65R14 Continental

L/H SIDE

4mm 175/65R14 Continental
4mm 175/65R14 Continental

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

POINT OF IMPACT

The vehicle sustained an impact on the front portion.

GENERAL DESCRIPTION OF DAMAGES

The front support panel, bumper assy, lower panel were dented.

For details of damages please refer to schedule attached.

REMARKS :

This survey was conducted strictly without prejudice.

PRESTIGE APPRAISER SERVICES

Vehicle No : GX 3476 G

Our Ref :

PS/005/01/17


Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
	<u>LIST ITEMS</u>			
1	front bumper	dented/cracked	\$ 780.00	\$ 780.00
8	front bumper clip	necessary	26.00	26.00
1	front bumper reinforcement	dented	288.00	288.00
1	front bumper lower grille	cracked	168.00	168.00
1	front grille	serviceable	468.00	-
1	front grille emblem	serviceable	55.00	-
4	front grille clip	necessary	25.00	25.00
1	R/H headlamp	holder cracked	418.00	418.00
1	aircon condenser	dented/bent	770.00	770.00
1	aircon pressure pipe	dented	168.00	168.00
1	aircon suction pipe	dented	165.00	165.00
1	radiator assy	dented/bent	740.00	740.00
1	radiator fan	damaged	420.00	420.00
1	radiator fan cowling	cracked	265.00	265.00
1	air filter hose	distorted	102.00	102.00
1	powering steering cooling pipe	dented	178.00	178.00
1	alternator	damaged	1,055.00	1,055.00
1	aircon compressor	damaged	1,182.00	1,182.00
1	front support panel	dented - repair	650.00	-
1	R/H front support panel dust cover	cracked	45.00	45.00
1	L/H front support panel dust cover	cracked	45.00	45.00
1	front lower cross member panel	dented	465.00	465.00
			<u>8,478.00</u>	<u>7,305.00</u>
		Less 10%	-	730.50
			\$ <u>8,478.00</u>	\$ <u>6,574.50</u>
	<u>S/NETT ITEM</u>			
1	front number plate		50.00	40.00
	<u>Labour Charges & Misc</u>			
	To dismantle & replace damaged parts, panel beat where necessary.		1,200.00	900.00
	To putty, apply primer & spray-paint on the affected portion.		850.00	600.00
	To remove/renew aircon condenser & refill gas.		180.00	140.00
	To remove/renew radiator assy.		180.00	100.00
	To check wiring functions.		250.00	80.00
			\$ <u>11,188.00</u>	\$ <u>8,434.50</u>

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **\$6,700.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **FIVE (5)** days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES



LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer











