

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007087/AEA3Q2
Date: 24/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900156682	
Claimant Vehicle No : 4948S,GBF9492Z	Insured Vehicle No : SMP1315Y	
Date of Loss: 27/06/2020	Nature of Claim: TP	Claim No: 5631212966SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: 4948S,GBF9492Z		
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No: 1KD2683887	
Reg. Date: 03/05/2017 (Man. Year: 2016)	Chassis No: JTFHT02P500215773	
Colour: Brown	Odometer: 89052 km	
Engine Capacity: 2982 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C	Rear Tyre Size: 195 R15C	
Front Left Side: Bridgestone 6 mm	Rear Left Side: Bridgestone 6 mm	
Front Right Side: Bridgestone 6 mm	Rear Right Side: Bridgestone 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,502.48	17,612.75	10,889.73	38.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,120.00	2,790.00	2,330.00	45.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	33,622.48	20,402.75	13,219.73	39.32
Approved Total (Overridden) (\$\$)		13,000.00		
(\$\$)	33,622.48	13,000.00	20,622.48	61.34
+ GST 7.00/7.00% (\$\$)	2,353.57	910.00	1,443.57	61.34
Nett Amount (\$\$)	35,976.05	13,910.00	22,066.05	61.34
+ Loss of Use (14.0 x S\$80.00/day) (\$\$)		1,120.00		
Nett Liability (\$\$)		15,030.00		

INSPECTION

Date of Assignment: 02/07/2020		
Date Inspected: 02/07/2020	Inspected At:	Lee Sheng Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-58/60 AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair: 10.0 days		

3/24/2021

Adjuster Report

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR BAG MODULE DRIVER SIDE	Activated	2,700.00 FL	*2,700.00 FL
2	1		*AIR BAG CONTROL UNIT	Activated	700.00 FL	*700.00 FL
3	1		*AIR BAG SIDE SENSOR	Activated	215.00 FL	*215.00 FL
4	1		*AIR BAG ASSY INSTR/PASSENGER	Activated	3,450.00 FL	*3,450.00 FL
5	1		*WIRE HARNESS AIR BAG	Not Necessary	72.00 FL	*- FL
6	1		*AIR BAG CLOCK WIRE	Activated	325.00 FL	*325.00 FL
7	1		*AIR BAG SENSOR	Activated	215.00 FL	*215.00 FL
8	1		*DASHBOARD	Torn	800.00 FL	*800.00 FL
9	1		*FRONT SEAT BELT RH	Activated	825.00 FL	*701.00 FL
10	1		*FRONT SEAT BELT LH	Activated	825.00 FL	*701.00 FL
11	1		*SEAT BELT BUCKLE LH	Not Necessary	350.00 FL	*- FL
12	1		*SEAT BELT BUCKLE RH	Not Necessary	350.00 FL	*- FL
13	1		*BLOWER MOTOR	Cracked	1,100.00 FL	*1,100.00 FL
14	1		*BLOWER UNIT	Cracked	1,100.00 FL	*1,100.00 FL
15	1		*BRAKE BOOSTER	Not Necessary	645.00 FL	*- FL
16	1		*BRAKE MASTER PUMP	Not Necessary	503.00 FL	*- FL
17	1		*WIPER PANEL ASSY	Not Necessary	667.00 FL	*- FL
18	1		*WIPER GARNISH	Not Necessary	565.00 FL	*- FL
19	2		*WIPER BLADE	Not Necessary	191.60 FL	*- FL
20	1		*WIPER CORNER GARNISH	N/S Dented	460.00 FL	*230.00 FL
21	1		*BONNET	Dented	845.00 FL	*757.00 FL
22	2		*BONNET HINGES	Not Necessary	118.00 FL	*- FL
23	1		*BONNET CABLE	Not Necessary	60.00 FL	*- FL
24	1		*BONNET INNER LOCK	Damaged	90.00 FL	*90.00 FL
25	1		*BONNET RUBBER	Cut	115.00 FL	*115.00 FL
26	6		*BONNET RUBBER CLIPS	Necessary	21.00 FL	*21.00 FL
27	1		*SUPPORT PANEL	Dented	375.00 FL	*375.00 FL
28	1		*BRACE PANEL	Bent	48.00 FL	*48.00 FL
29	1		*FRONT BUMPER	Missing	595.00 FL	*595.00 FL
30	2		*FRONT BUMPER RETAINER RH/LH	Damaged	300.00 FL	*300.00 FL
31	1		*FRONT BUMPER BEAM BRACKET	Dented	450.00 FL	*450.00 FL
32	1		*FRONT BUMPER CENTRE BRACKET	Dented	250.00 FL	*250.00 FL
33	1		*FRONT BUMPER REINFORCEMENT	Bent	355.00 FL	*355.00 FL
34	1		*FRONT BUMPER LOWER GRILLE	Deformed	215.00 FL	*215.00 FL
35	1		*FRONT BUMPER LOWER REINFORCEMENT	Bent	160.00 FL	*160.00 FL
36	1		*HORN HIGH PITCHED	Not Necessary	118.00 FL	*- FL
37	2		*HEADLAMP RH/LH	Cracked	1,796.00 FL	*1,796.00 FL
38	1		*BONNET STAND	Not Necessary	30.00 FL	*- FL
39	1		*WIPER TANK	Deformed	90.00 FL	*90.00 FL
40	1		*WIPER TANK MOTOR	Not Necessary	242.00 FL	*- FL
41	1		*INTER COOLER	Not Necessary	1,336.00 FL	*- FL
42	1		*AIR CON CONDENSER	Deformed	1,445.00 FL	*1,095.00 FL
43	1		*AIR CON DISCHARGE PIPE	Not Necessary	220.00 FL	*- FL
44	1		*AIR CON SUCTION PIPE	Not Necessary	585.00 FL	*- FL
45	1		*AIR CON DRIER	Not Necessary	205.00 FL	*- FL
46	1		*RADIATOR	Bent	2,115.00 FL	*1,495.00 FL
47	1		*RADIATOR TOP HOSE	Not Necessary	39.00 FL	*- FL
48	1		*RADIATOR LOWER HOSE	Not Necessary	39.00 FL	*- FL
49	1		*RADIATOR FAN COWLING BIG	Cracked	315.00 FL	*315.00 FL
50	1		*RADIATOR FAN COWLING SMALL	Cracked	285.00 FL	*285.00 FL
51	1		*AIR CLEANER ASSY	Not Necessary	765.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*CENTRAL LOCK SYSTEM	Not Necessary	39.00 FL	*- FL
53	1		*RADIATOR FAN MOTOR	Not Necessary	1,319.00 FL	*- FL
54	1		*AIR CON FAN MOTOR	Damaged	1,319.00 FL	*923.00 FL
55	1		*FRONT GRILLE BASE	Missing	500.00 FL	*500.00 FL
56	1		*FRONT GRILLE TOP GARNISH	Missing	200.00 FL	*200.00 FL
57	1		*FRONT GRILLE LOWER GARNISH	Missing	345.00 FL	*345.00 FL
58	1		*SUPPORT LOWER MEMBER	Repair	795.00 FL	*- FL
59	1		*SUPPORT SIDE PANEL RH/LH	N/S Distorted	390.00 FL	*195.00 FL
60	2		*SUPPORT TOP GARNISH RH/LH	Not Necessary	310.00 FL	*- FL
61	1		*HORN LOW PUTCHED	Not Necessary	118.00 FL	*- FL
62	1		*SET FRONT NUMBER PLATE & BASE	Missing	50.00 FS	*50.00 FS
63	1		*BRAKE BOSTRE PIPE	Distorted	550.00 FL	*210.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	35,615.60	23,467.00
- List Item Discount on L Items 20.00/25.00% (\$\$)	7,113.12	5,854.25
Total Parts (\$\$)	28,502.48	17,612.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	KNOCKING ,CUTTING ,JACKING WELDING ETC	New	2,200.00	1,200.00
2	SPRAY PAINTING	New	1,800.00	800.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	100.00	30.00
4	REMOVE & REFIX DASHBOARD	New	280.00	220.00
5	REMOVE & REFIX AIR BAG & SEAT BELT	New	280.00	280.00
6	TOWING	New	80.00	60.00
7	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	80.00
8	TO CHECK & RESET SYSTEM	New	180.00	120.00
Gross Labour Cost (S\$)			5,120.00	2,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >