

Your Ref : S0M02QCC

Date: 20th July 2020

Our Ref : CS4/ASM20007092/Pvce2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Yvonne Ang

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBA 9799R
ACCIDENT ON 01/07/2020

Instruction was received to inspect the vehicle Reg. No. GBA 9799R. The inspection was conducted on 09/07/2020 at the premises of M/s Ethoz Group Ltd, 30 Bukit Batok Crescent, Singapore 658075.

The following vehicle information was recorded:

Registration Number	: GBA 9799R
Make/Model	: Nissan Cabstar 3.0 5M/T ABS 2DR 2WD 3.4T
Year of Registration	: 2008
Body Colour	: White
Chassis Number	: JN1SC2F24Z0800262
Engine Capacity	: 2953 cc
Speedometer Reading	: Nil

The whole vehicle was burnt down badly. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Market Value	S\$ 13,800.00
Less: LTA Reimbursement Value (RV)	(S\$ 11,251.00)
Nett Liability	<u>S\$ 2,549.00</u> =====

Vehicle Inspected By:



SHERWIN BEH SWEE YANG
Technical Investigator



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.