

Our Job Ref No 305409753

Date : 09.07.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. SHA8277R CTPL

06.07.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG --- SBR1000A

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

\$2,050.00

Final Lumpsum Repair cost**\$2,050.00**3. Estimated normal period for repairs: 2 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**


5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 14/7/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305409753
 REGN NO : SHA8277R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 25.08.2016
 DATE/TIME IN : 07.07.2020 14:30
 ACCIDENT DATE : 06.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	de✓
0002	04-01-0103-0637-G	I40VC BRKT ASSY-FR BPR UP	1	22.40	20.00	17.92	? Xnn
0003	04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68	? Xnn
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60	de✓
0005	04-01-0103-0781-A	I40VC LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40	? Xnn
0006	04-01-0103-0574-A	I40VC PANEL-FENDER LH+	1	663.00	20.00	530.40	ht✓
0007	04-01-0103-0657-G	I40V2 GUARD ASSY-FR WHEEL	1	174.90	20.00	139.92	art✓
0008	04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	112.50	20.00	90.00	de✓
0009	03-01-0103-0098-G	I40VC WHEEL ASSY-STEEL	1	325.30	20.00	260.24	Ry

SUB-TOTAL : 3,027.92

JOB NATURE

0000 L PANEL BEATING(rep. bonnet & v.mirror)
 0001 23-502 SPRAYPAINT ON AFFECTED AREA

700.00 420.

650.00 400.

2,024.60
 -20%
 1,619.68

960
 2,579.68
 -20%
 2,063.74

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305409753
REGN NO : SHA8277R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 07.07.2020 14:3
ACCIDENT DATE : 06.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 17-01	CHECK ALL LIGHTING	50.00	30	
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30	
0004 20-08	ADJUST FRONT WHEEL ALIGNMENT	120.00	80	
		SUB-TOTAL : 1,570.00		

TOTAL : 4,597.92

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanferin 97445749
WP, 8/7/20 @ 4pm
Lumpsum \$2,050/-
Resumy after repair
Tanferin @ 11h auto.com
02-03 days