



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

page 1/3

Plate No. SLX 3481G

Model Hyundai Avante

Date of Accident : 05-07-2020

Time of Accident : 20 : 20

Venue : Bt Batok East Ave

Qty	Parts Description	Estimated Parts Price
1	Rear bumper assy 489.10	\$ Bu 742.00 ✓
2	Rear bumper bracket	\$ L 94.00 X
2	Rear bumper retainer	\$ ALSDIR 96.00 L+
1	Rear reinforcement bar assy 270	\$ DIS/CM 789.00 ✓
1	Rear bootlid assy	\$ Bu 917.00 ✓
1	Rear bumper left mudflap	\$ L 152.00 X
1	Rear bumper right mudflap	\$ L 152.00 X
1	Rear bootlid lock mechanism	\$ R 145.00 X
1	Rear bootlid lock catch	\$ R 98.00 X
1	Rear bootlid weatherstrip	\$ L 218.00 X
1	Rear left bootlid tail lamp 188.50	\$ G 362.00 ✓
1	Rear right bootlid tail lamp	\$ L 362.00 X
1	Rear bootlid Hyundai logo 61.60	\$ R 95.00 ✓
1	Rear right tail lamp	\$ L 463.00 X
1	Rear right tail lamp gutter	\$ L 58.00 X
1	Rear right tail lamp lower panel	\$ R 262.00 X
1	Rear left tail lamp 294.50	\$ G 463.00 ✓
1	Rear left tail lamp gutter	\$ L 58.00 X
1	Rear left tail lamp lower panel	\$ R 262.00 X
1	Rear end lower panel	\$ R 572.00 X
1	Rear end panel top garnish	\$ L 118.00 X
1	Rear bumper sponge 109	\$ CM 278.00 ✓
2	Rear reinforcement panel head	\$ L 446.00 X
		\$ 7,202.00
	Less 20%	\$ 1,440.40
		\$ 5,761.60

NOT Authorized
LI Imp @ 2550k
Recovery After Paint
4 days



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

page 3/3

Car Plate No. **SLX 3481G**
Model **Hyundai Avante**

Date of Accident : **05-07-2020**
Time of Accident : **20 : 20**
Venue : **Bt Batok East Ave**

<u>Parts Description</u>	<u>Labour Charges</u>
Labour for panel beating, cut, weld , straighten rear affected area and replace rear damage parts	\$ 1,600.00 <i>400</i>
To putty & spray painting rear portion	\$ 1,600.00 <i>600</i>
To check rear lighting and wiring	\$ 50.00 <i>20</i>
To remove and install rear bootlid lock mechanism	\$ <i>12</i> 80.00 <i>X</i>
To remove and install rear inner trim to facilitate the repair	\$ <i>12</i> 120.00 <i>X</i>
To apply anti rust proofing to rear affected area	\$ 120.00 <i>30</i>
To remove and install rear bumper reverse sensor	\$ 80.00 <i>50</i>
Total Labour	\$ 3,650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts	\$ 6,521.60
Total Labour	\$ 3,650.00
Total Repair Cost	\$ 10,171.60



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

No. SLX 3481G
 Model Hyundai Avante

Date of Accident : 05-07-2020

Time of Accident : 20 : 20

Venue : Bt Batok East Ave

Parts Description

Special Nett Items

- | | |
|----|--|
| 10 | Rear bumper clips |
| 4 | Rear end lower panel top garnish clips |
| 1 | Rear end lower panel sealant |
| 2 | Rear bumper reverse sensor |
| 2 | RH & LH mudguard sealant |
| 1 | Rear no plate with garnish |

Estimated Parts Price

\$	nn	50.00	✓
\$	nn	20.00	X
\$	nn	120.00	X
\$	shon	250.00	180.00
\$	nn	240.00	X
\$	sn	80.00	X
\$		760.00	

Total Parts \$ 6,521.60