

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20007112/AVF3E2

Date: 08/02/2021

REFERENCE

| | | | | | |
|-------------------|----------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | LEONG KOK MENG | Policy No: | 2100498857 | | |
| Date of Loss: | 04/07/2020 | Nature of Claim: | OD | Claim No: | 2809324744SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-------------------------------|-------------|-------------------|
| Reg No: | SLK7949S | | |
| Make & Model: | AUDI A3, 999cc SEDAN TFSI (A) | Engine No: | CHZ142329 |
| Reg. Date: | 26/01/2017 (Man. Year: 2016) | Chassis No: | WAUZZZ8V8H1016421 |
| Colour: | White | Odometer: | 68657 km |
| Engine Capacity: | 999 cc | | |
| Market Value/New Car Price: | S\$70,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre tread depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|------------------|-----------------|------------------|--------------|
| Parts | 13,646.00 | 3,902.16 | 9,743.84 | 71.40 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,872.00 | 2,072.00 | 5,800.00 | 73.68 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 21,518.00 | 5,974.16 | 15,543.84 | 72.24 |
| - Excess (S\$) | 800.00 | 800.00 | 0.00 | 0.00 |
| (S\$) | 20,718.00 | 5,174.16 | 15,543.84 | 75.03 |
| + GST 7.00/7.00% (S\$) | 1,450.26 | 362.19 | 1,088.07 | 75.03 |
| Nett Amount (S\$) | 22,168.26 | 5,536.35 | 16,631.91 | 75.03 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 08/07/2020 | | |
| Date Inspected: | 08/07/2020 | Inspected At: | Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|---------------------------|--------------------------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 1,894.00 FS | *1,515.20 FS |
| 2 | 1 | | *FRONT BUMPER FIXING PARTS | Not Necessary | 176.00 FS | *- FS |
| 3 | 1 | | *FRONT BUMPER GUIDE SECTION - LH | Not Necessary | 36.00 FS | *- FS |
| 4 | 1 | | *FRONT BUMPER GRILLE - CENTRE | Cracked | 151.00 FS | *120.40 FS |
| 5 | 1 | | *FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | Not Necessary | 505.00 FS | *- FS |
| 6 | 1 | | *FRONT BUMPER CLOSING ELEMENT - LH | Not Necessary | 280.00 FS | *- FS |
| 7 | 1 | | *FRONT BUMPER COVER TRIM - LH | Not Necessary | 153.00 FS | *- FS |
| 8 | 1 | | *WHEEL HOUSING LINER ADAPTER - LH | Not Necessary | 36.00 FS | *- FS |
| 9 | 1 | | *RADIATOR GRILLE | Cracked | 1,338.00 FS | *1,070.40 FS |
| 10 | 1 | | *RADIATOR GRILLE CLOSING ELEMENT | Cracked | 180.00 FS | *143.60 FS |
| 11 | 1 | | *AIRCON STICKER | Necessary | 7.00 FS | *5.36 FS |
| 12 | 1 | | *CAUTION SIGN STICKER | Necessary | 13.00 FS | *10.24 FS |
| 13 | 1 | | *FRONT BUMPER SIDE REINFORCEMENT BEAM | Bent | 681.00 FS | *571.60 FS |
| 14 | 1 | | *FRONT BUMPER FOAM FILLER PIECE | Cracked | 178.00 FS | *149.60 FS |
| 15 | 1 | | *FOAM FILLER PIECE COVER | Cracked | 115.00 FS | *96.40 FS |
| 16 | 1 | | *TOP FOAM FILLER PIECE COVER | Not Necessary | 115.00 FS | *- FS |
| 17 | 1 | | *FRONT BUMPER AIR GUIDE GRILLE - LH | Missing | 177.00 FS | *141.20 FS |
| 18 | 1 | | *SIGNAL HORN RETAINER - LH HIGH TONE | Not Necessary | 188.00 FS | *- FS |
| 19 | 1 | | *LED HEADLIGHT - LH | Not Necessary | 5,193.00 FS | *- FS |
| 20 | 2 | | *LIFT CYLINDER - LH / RH | Not Necessary | 268.00 FS | *- FS |
| 21 | 1 | | *LIFT CYLINDER HOSE | Not Necessary | 64.00 FS | *- FS |
| 22 | 1 | | *WASH WATER RESERVOIR | Not Necessary | 190.00 FS | *- FS |
| 23 | 1 | | *LOCK CARRIER | Not Necessary | 685.00 FS | *- FS |
| 24 | 1 | | *AIRCON CONDENSER | Not Necessary | 519.00 FS | *- FS |
| 25 | 1 | | *READY MIX COOLANT | Not Necessary | 86.00 FS | *- FS |
| 26 | 2 | | *RADIATOR AIR GUIDE - LH / RH | Cracked | 46.00 FS | *18.16 FS |
| 27 | 1 | | *RADIATOR AIR GUIDE - UPPER CENTRE | Not Necessary | 12.00 FS | *- FS |
| 28 | 1 | | *FRONT NO PLATE | Dented | 60.00 FS | *60.00 FS |
| 29 | 1 | | *SUNDRIES | Not Necessary | 300.00 FS | *- FS |
| | | | | | Total Parts (\$\$) | 13,646.00 3,902.16 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNITS AND POWER MODULES. TO CARRY OUT CALIBRATION | New | 350.00 | 0.00 |
| 2 | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS | New | 1,200.00 | 0.00 |
| 3 | TO DISMANTLE AND RENEW FRONT BUMPER. TO REPAIR BONNET. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 3,850.00 | 500.00 |
| 4 | TO RESPRAY FRONT BUMPER AND BONNET | New | 2,000.00 | 1,100.00 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| 6 | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY (SUPPLEMENTARY) | New | 280.00 | 280.00 |
| Gross Labour Cost (\$\$) | | | 7,872.00 | 2,072.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >