

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 2201P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CRUMPLED	602.50	602.50
1	FRONT BUMPER SIDE RETAINER RH	BROKEN	45.50	45.50
1	FRONT BUMPER SIDE RETAINER LH	BROKEN	45.50	45.50
1	FRONT BUMPER LOWER SPOILER	SCRATCHED	262.50	262.50
1	FRONT FOG LAMP RH	SERVICEABLE	227.40	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	315.20	-
1	FRONT HEADLAMP RH	SCRATCHED	615.30	615.30
1	FRONT HEADLAMP LOWER BRACKET RH	CRACKED	96.20	96.20
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	783.10	-
1	FRONT FENDER INNER SHIELD RH	SERVICEABLE	157.50	-
1	FRONT GRILLE	CRACKED	245.80	245.80
	LESS 20% DISCOUNT		-679.30	-382.66
			2,717.20	1,530.64
	SPECIAL NETT ITEMS			
1	FRONT FENDER INNER SHIELD CLIPS (SN)	SERVICEABLE	40.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
			80.00	30.00
	<u>LABOUR</u>			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		120.00	20.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		600.00	300.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	100.00	-
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		80.00	40.00

Report Ref No. CS/SMO20007117/QUtf3e2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		700.00	500.00
			1,600.00	860.00
	GRAND TOTAL		4,397.20	2,420.64

RECOMMENDED COST OF REPAIRS		2,420.64
(REPAIR COST NOT CONCLUDE)		·

Report Ref No. CS/SMO20007117/QUtf3e2

CHUA KANG SENG

**Licensed Appraiser**