LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. Our File No: CC3/AIG20007130/AVF3E2 AIG Building, 78 Shenton Way #07-16

09/03/2021 Date: Singapore 079120

REFERENCE

Insured/Claimant: ACMECA COOLINGSYSTEM & ENGINEERING PTE LTD 1900000222 Policy No:

Date of Loss: 06/07/2020 Nature of Claim: OD Claim No: 2279140103SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKG1989Z

AUDI A5 SPORTBACK, 2.0 TFSI QUATTRO (A) CVK073959 Make & Model: Engine No:

Reg. Date: 28/01/2019 (Man. Year: 2018) Chassis No: WAUZZZF58KA012976

Colour: Black Odometer: 35374 km

1984 cc **Engine Capacity:** Market Value/New Car Price: S\$150,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Engine Modification: Pre-accident Condition: Handbrake (Serviceable): Yes No

CONDITION OF TYRES

245/40R18 Rear Tyre Size: Front Tyre Size: 245/40R18 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		21,647.00	13,752.48	7,894.52	36.47
Miscellaneous Items		0.00	0.00	0.00	
Labour		16,164.00	8,532.00	7,632.00	47.22
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	37,811.00	22,284.48	15,526.52	41.06
	- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
	(S\$)	36,211.00	20,684.48	15,526.52	42.88
	+ GST 7.00/7.00% (S\$)	2,534.77	1,447.91	1,086.86	42.88
	Nett Amount (S\$)	38,745.77	22,132.39	16,613.38	42.88

INSPECTION

Date of Assignment: 08/07/2020

Premium Automobiles Pte Ltd (HQ)

Date Inspected: 08/07/2020 Inspected At: 55 UBI ROAD 1

Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: **ADRIAN LING VERON CHEN** Manager:

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	2,190.00 FS	*1,840.00 FS
2	2		*ULTRASOUND SENDOR SUPPORT-LH/RH	Damaged	98.00 FS	*80.80 FS
3	1		*RADIATOR GRILLE COVER-UPPER	Not Necessary	178.00 FS	*- FS
4	1		*FRONT BUMPER TOP COVER	Cracked	120.00 FS	*100.40 FS
5	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.80 FS
6	1		*AIRCON STICKER	Necessary	7.00 FS	*5.68 FS
7	1		*QUATTRO INSCRIPTION	Not Necessary	102.00 FS	*- FS
8	1		*BONNET	Distorted	2,682.00 FS	*2,253.60 FS
9	1		*BONNET ATTACHMENT PARTS	Not Necessary	116.00 FS	*- FS
10	2		*BONNET LID HINGE-LH/RH	Not Necessary	790.00 FS	*- FS
11	1		*BONNET IMPACT PROTECTION-LH/RH/CENTRE (3pcs)	Necessary	78.00 FS	*64.88 FS
12	1		*BONNET SOUND ABSORBER	Not Necessary	323.00 FS	*- FS
13	1		*FENDER LEDGE COVER-INNER	Not Necessary	34.00 FS	*- FS
14	1		*FENDER LEDGE COVER-OUTER	Not Necessary	15.00 FS	*-FS
15	1		*BONNET STRIKER-RH	Bent	47.00 FS	*39.44 FS
16	1		*BONNET LID LOCK	Not Necessary	202.00 FS	*-FS
17	1		*BONNET LID LOCK CABLE	Not Necessary	69.00 FS	*- FS
18	1		*LED HEADLIGHT-RH	Cracked	7,438.00 FS	*6,249.60 FS
19	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Necessary	714.00 FS	*- FS
20	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	707.00 FS	*- FS
21	1		*LED WITH HEAT SINK-RH	Not Necessary	1,086.00 FS	*- FS
22	1		*HEADLIGHT HOSE	Not Necessary	34.00 FS	*- FS
23	1		*FRONT BUMPER	Deformed	2,142.00 FS	*1,800.80 FS
24	1		*FRONT BUMPER FIXING PARTS	Not Necessary	383.00 FS	*-FS
25	1		*LOCK CARRIER	Cracked	956.00 FS	*803.20 FS
26	1		*READY MIX COOLANT	Necessary	169.00 FS	*141.44 FS
27	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	15.00 FS	*- FS
28	1		*DOOR TRIM-LH/RH	N/s Necessary	300.00 FS	*125.60 FS
29	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
30	1		*SUNDRIES	Necessary	300.00 FS	*2.24 FS
31	1		*FRONT FENDER EMBLEM TRIM RHS (Supplementary)	Necessary	150.00 FS	*125.60 FS
32	1		*BRACKET LOCK CARRIER (Supplementary)	Cracked	129.00 FS	*108.40 FS
F=Fra	anchise	part. S=SpcN	Nett.			
				Total Parts (S\$)	21,647.00	13,752.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER/REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM.	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE. TO CARRY OUT CALIBRATION.	New	400.00	250.00
3	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL RHS WING MIRROR ASSYS.	New	800.00	360.00
4	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGES AIR COOLER,RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
5	TO DISMANTLE AND RENEW FRONT BUMPER AND BONNET. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.RE	V New	4,800.00	2,250.00
6	TO RESPRAY FRONT BUMPER, BONNET,HINGES,RHS FRONT DOOR AND LHS FRONT DOOR.	New	4,500.00	2,200.00
7	TO CARRY OUT PRE-DIAGNOSTIC CHECK AND POST-DIAGNOSTIC CHECK.	New	384.00	192.00
8	TO REPAIR RHS FRONT FENDER. (Supplementary)	New	800.00	250.00
9	TO RESPRAY RHS FRONT FENDER. (Supplementary)	New	1,000.00	550.00
10	TO REPAIR RHS UPPER A-PILLAR. (Supplementary)	New	800.00	250.00
11	TO REPSRAY RHS UPPER A-PILLAR. (Supplementary)	New	1,000.00	550.00
	Gross Labou	r Cost (S\$)	16,164.00	8,532.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.