

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 19 Aug 2020

## **Preliminary Advice**

Insured Vehicle No : YN9390U  
TP Vehicle No : GBK3691D  
Make : TOYOTA DYNA 150  
Date of Inspection : 09/08/2020  
Inspection At : AUTOMOBILE HUB ENTERPRISE  
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT  
SINGAPORE 417883  
Accident Date : 04/07/2020  
Assignment Date : 08/07/2020  
Est. Duration of Repair : 4

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 9,302.48 |
| Revised Amount              | :S\$ | 5,474.67 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 5,474.67 |
| Lump Sum Repair             | :S\$ | 4,300.00 |

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : survey on wp