

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007135/KES3Q2

Date: 09/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100312037

Claimant
Vehicle No : GBH1604K **Insured Vehicle No :** SJL1283L

Date of Loss: 06/07/2020 Nature of Claim: TP Claim No: 7904506783SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH1604K		
Make & Model:	TOYOTA HIACE, 2.5 (A)	Engine No:	HIDDEN
Reg. Date:	01/02/2018 (Man. Year: 2018)	Chassis No:	KDH2010228318
Colour:	Metallic Grey	Odometer:	55460 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,359.08	3,020.94	2,338.14	43.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,570.00	700.00	30.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,629.08	4,590.94	3,038.14	39.82
+ GST 7.00/7.00% (\$\$)	534.04	321.37	212.67	39.82
Nett Amount (\$\$)	8,163.12	4,912.31	3,250.81	39.82
+ Loss of Use (6.0 x S\$90.00/day) (\$\$)		540.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,454.31		

INSPECTION

Date of Assignment: 08/07/2020

Date Inspected: 09/07/2020 Inspected At:

City Auto Pte Ltd (Sin Ming) (HQ)
Block 8 Sin Ming Road #01-58/60/62
Sin Ming Est
Singapore 575643

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,021.70 FL	*2,021.70 FL
2	1		*TAILGATE LOCK	Jammed	265.74 FL	*265.74 FL
3	1		*TAILGATE LOCK COVER	Dented	122.30 FL	*122.30 FL
4	1		*TAILGATE LOGO	Necessary	61.70 FL	*61.70 FL
5	1		*TAILGATE EMBLEM -HIACE	Necessary	49.50 FL	*49.50 FL
6	1		*TAILGATE EMBLEM -SUPER GL	Necessary	43.67 FL	*43.67 FL
7	1		*TAILGATE OUTER CHROME MOULDING	Serviceable	240.71 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Serviceable	402.70 FL	*- FL
9	1		*TAILGATE STRIKER	Repair	122.47 FL	*- FL
10	1		*TAILGATE INNER TRIM	Serviceable	298.40 FL	*- FL
11	1		*REAR BUMPER	Bent	396.90 FL	*396.90 FL
12	2		*REAR BUMPER RETAINER	Distorted	80.66 FL	*80.66 FL
13	12		*REAR BUMPER CLIPS	Necessary	50.52 FL	*50.52 FL
14	1		*REAR KEYLESS ENTRY ANTENNE	Serviceable	212.67 FL	*- FL
15	1		*REAR STEP PANEL	Bent	360.98 FL	*360.98 FL
16	1		*REAR END PANEL OUTER	Bent	315.95 FL	*315.95 FL
17	1		*REAR END PANEL INNER	Repair	891.75 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	178.30 FL	*178.30 FL
19	2		*TAIL LAMP	Serviceable	665.50 FL	*- FL
20	2		*TAIL LAMP LOWER COVER	Serviceable	283.32 FL	*- FL
21	1		*TAILGATE STICKER -70KM/H	Necessary	10.00 FS	*10.00 FS
22	1		*TAILGATE STICKER 6 PAX	Necessary	10.00 FS	*10.00 FS
23	1		*GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,125.44	4,007.92
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,766.36	986.98
Total Parts (\$\$)	5,359.08	3,020.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
2	TO REMOVE AND REFIT REAR TRIMS AND UPHOLSTERY	New	120.00	60.00
3	TO CHECK WIRING AND LIGHTING	New	50.00	20.00
4	TO SPRAY RUBBERIZED UNDER-COATING	New	150.00	60.00
5	TO SUPPLY PANEL SEALANT AND TO SEAL OFF ALL WELD SPOT SEAM AND GAPS	New	150.00	30.00
6	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	900.00	700.00
7	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	800.00	600.00
Gross Labour Cost (\$\$)			2,270.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >