Page 1 of 3 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20007143/R1VF3E2

Date: 16/07/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900153158 Claimant Vehicle SML9029S Insured Vehicle No: SLS3391J

ΤP Date of Loss: 07/07/2020 Nature of Claim: Claim No: 4257685397SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SML9029S

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2606398 Reg. Date: 17/07/2006 (Man. Year: 2006) Chassis No: ZNE100312455 Colour: Odometer: 178383 km Grey

Engine Capacity: 1794 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

195/65 R15 Front Tyre Size: 195/65 R15 Rear Tyre Size: Front Left Side: Rear Left Side: Triangle 6 mm Triangle 6 mm Rear Right Side: Front Right Side: Triangle 6 mm Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$	0.00	0.00	0.00	

INSPECTION

08/07/2020 Date of Assignment:

Date Inspected: 09/07/2020 Inspected At: V Tech Auto Service (soon Lee) (HQ) NO.1 SOON LEE STREET, #06-04,

PIONEER CENTRE, SINGAPORE 627605

Singapore 627605

Estimated Period of Repair: 5.0 days

Manager: VERON CHEN MOHD RASUL Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR RH FENDER	Repair	0.00 F	*-F
4	1		*REAR RH WHEEL RIM	Scratched	0.00 F	*- F
5	1		*REAR RH DOOR	Repair	0.00 F	*- F
6	1		*REAR RH SHOCK ABSORBER	Bent	0.00 F	*-F
7	1		*REAR KNUCKLE BEARING RH	Bent	0.00 F	*-F
F=Fra	anchise	part.		_		
				Total Parts (S\$)	0.00	0.00
				_		

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >