

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19006523/R1PA3Q2-1

Date: 27/07/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> YP7134X	<b>Insured Vehicle No :</b>	SHC2233X
Date of Loss: 03/04/2019	Nature of Claim: TP	Claim No: MCT19040064

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>YP7134X</b>		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C75294
Reg. Date:	07/09/2017 (Man. Year: 2017)	Chassis No:	FEB21EA21584
Colour:	White	Odometer:	36791 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C (D)
Front Left Side:	Austone 7 mm	Rear Left Side:	Austone 7/7 mm
Front Right Side:	Austone 7 mm	Rear Right Side:	Austone 7/7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,125.10	3,571.07	554.03	13.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	940.00	540.00	36.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,605.10</b>	<b>4,511.07</b>	<b>1,094.03</b>	<b>19.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>(S\$)</b>	5,605.10	3,600.00	2,005.10	35.77
<b>+ GST 7.00/7.00% (S\$)</b>	392.36	252.00	140.36	35.77
<b>Nett Amount (S\$)</b>	<b>5,997.46</b>	<b>3,852.00</b>	<b>2,145.46</b>	<b>35.77</b>
<b>+ Loss of Use (5.0 x S\$150.00/day) (S\$)</b>		750.00		
<b>(S\$)</b>		4,602.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>2,301.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,308.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,250.00</b>		

### INSPECTION

Date of Assignment: 11/04/2019

Date Inspected: 22/10/2019 Inspected At:

Sin Sheng Engineering Services  
7 Sin Ming Industrial Estate Sector C,

#01-82,  
Singapore 575642

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 02 Dec 2019)	
<b>Parts:</b>	N/A	mitsubishi canter 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP7134X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR ,RHS	Bent	2,001.44 FL	*2,001.44 FL
2	2		*DOOR HINGE	Serviceable	528.20 FL	*- FL
3	1		*FRONT BUMPER	Bent	948.37 FL	*948.37 FL
4	1		*BUMPER BRACKET ,RHS	Serviceable	210.50 FL	*- FL
5	1		*BUMPER CORNER ,RHS	Scratched	353.71 FL	*353.71 FL
6	1		*HEADLAMP ,RHS	Cracked	470.69 FL	*470.69 FL
7	1		*HEADLAMP GARNISH	Cut	34.48 FL	*34.48 FL
8	1		*SIGNAL LAMP ,RHS	Cracked	270.39 FL	*270.39 FL
9	1		*SIDE LAMP ,RHS	Cracked	211.96 FL	*211.96 FL
10	1		*STEP GARNISH ,RHS	Deformed	470.39 FL	*470.39 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,500.13</b>	<b>4,761.43</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,375.03	1,190.36
<b>Total Parts (S\$)</b>	<b>4,125.10</b>	<b>3,571.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT AND REPAIR RIGHT SIDE BODY TO DISMANTLE /REPLACE ABOVEMENTIONED PARTS	New	750.00	500.00
2	TO SPRAY PAINTING	New	650.00	400.00
3	TO APPLY TUFF KOTE	New	80.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>1,480.00</b>	<b>940.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**