

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile								
EQ IN:	SURANCE COM	PANY LTD	Ref: CC3/EQI15009394/Kwa3q2					
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date: 30-06-2016 Code: EQI						
1.	Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SJA 5796E	Veh. Inspected	SHC 5328L				
	Policy No.	DMPPHQ14-003765	Coverage (\$)	0.00				
	Claim No.	DM15HO00989/RA	Excess (\$)	0.00				
4	Assign From		Assign Date	05/06/2015				
2.		Vehicle Partic	culars & Condition					
	Make & Model	RENAULT LATITUDE (A)	c.c	1995				
	Engine No.	HIDDEN	Year of Reg.	2014				
	Chassis No.	VF1ABL15AUC276880	Colour	METALLIC WHITE/RED				
	Odometer	137900	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	NIL				
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make	Balance				
-	R/H Front Tyre	215/60 R16	FALKEN	4 mm				
-	L/H Front Tyre	215/60 R16	FALKEN	4 mm				
-	R/H Rear Tyre	215/60 R16	GOODYEAR	2 mm				
_	L/H Rear Tyre	215/60 R16	GOODYEAR	2 mm				
4.		•	on of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S	BODY.					
	DAMAGES SEE DI	-						
5.		General	Information					
4	Accident Date	04/06/2015	Inspection Date	05/06/2015				
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD						
		NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	Estimate Days of Repair							
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days							



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5328L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	SERVICEABLE	968.78	-
1	HEADLAMP RH	SERVICEABLE	911.10	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	602.95	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,188.20	-
1	DOOR MIRROR RH	SERVICEABLE	1,141.08	-
1	DOOR MOULDING FRT RH	SERVICEABLE	136.01	-
1	DOOR SEAL FRT RH	SERVICEABLE	56.02	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	198.55	-
1	DOOR HANDLE CAP FRT RH	SERVICEABLE	20.34	-
1	DOOR HANDLE SEAL FRT RH	SERVICEABLE	6.07	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	759.61	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,188.20	-
1	DOOR HANDLE OUTER RR RH	SERVICEABLE	198.55	-
1	DOOR MOULDING RR RH	SERVICEABLE	137.21	-
	LESS 10% DISCOUNT		-951.27	-
			8,561.40	-
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET WHEELARCH CLIP RH (SN)	NOT NECESSARY	66.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	CAP HUB RH FRT (SN)	SERVICEABLE	35.00	-
1	RIM RH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE RH FRT (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER 'TRANS-CAB' RH (SN)	NECESSARY	80.00	60.00
1	DOOR STICKER 'CLASSIC' RH (SN)	NECESSARY	30.00	15.00
1	DOOR STICKER '6555-3333' (SN)	NECESSARY	80.00	60.00
			1,138.00	135.00

Report Ref No. CC3/EQI15009394/Kwa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

890.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FENDER PANEL FRT RH,DOOR PANEL FRT RH,ROCKER PANEL OUTER RH AND DOOR PANEL REAR RH .		1,400.00	300.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,500.00	440.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL ALIGNMENT.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
			3,800.00	755.00
	GRAND TOTAL		13,499.40	890.00

Report Ref No. CC3/EQI15009394/Kwa3q2

KONG SENG CHEONG

RECOMMENDED COST OF REPAIRS

Licensed Appraiser