

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007153/KES3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900000222

Claimant
Vehicle No : GBA9953L **Insured Vehicle No :** SKG1989Z

Date of Loss: 06/07/2020 Nature of Claim: TP Claim No: 2279140103SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA9953L	Engine No:	4D56UCBB8699
Make & Model:	MITSUBISHI L200, 2.5 D Double Cabin (A)	Chassis No:	MMBJRKB407D157814
Reg. Date:	14/05/2008 (Man. Year: 2008)	Odometer:	425653 km
Colour:	Metallic Blue		
Engine Capacity:	2477 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/70 R16	Rear Tyre Size:	265/70 R16
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,859.00	1,593.00	3,266.00	67.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,130.00	510.00	31.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,499.00	2,723.00	3,776.00	58.10
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	6,499.00	2,300.00	4,199.00	64.61
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
Nett Liability (S\$)		2,780.00		

INSPECTION

Date of Assignment: 09/07/2020

Date Inspected: 09/07/2020 Inspected At:

Supreme Auto Service Pte Ltd (HQ)
176 Sin Ming Drive #02-01, Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	978.00 F	*- FN
2	1		*REAR END PANEL	Repair	463.00 F	*- FN
3	1		*REAR TAIL LAMP	Serviceable	280.00 F	*- FN
4	1		*REAR BUMPER	Bent	2,380.00 FS	*885.00 FS
5	1		*REAR BUMPER TOP RUBBER	Distorted	280.00 FS	*280.00 FS
6	1		*REAR BUMPER BRACKET	Distorted	158.00 FS	*158.00 FS
7	1		*REVERSE SENSOR	Scratched	250.00 FS	*200.00 FS
8	1		*STICKER	Necessary	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	4,859.00	1,593.00
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	0.00
Total Parts (S\$)	4,859.00	1,593.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE ALL THE PARTS MENTIONED ABOVE ,KNOCKING & STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	700.00	500.00
2	TO SPRAY PAINTING AFFECTED AREAS	New	700.00	550.00
3	TO INSTALL REVERSE SENSOR	New	80.00	50.00
4	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	80.00	30.00
5	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	80.00	0.00
Gross Labour Cost (\$)			1,640.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >