



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5544R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BONNET	TO REPAIR SEE LABOUR	3,000.00	-
1	REAR BONNET WEATHERSTRIP	SERVICEABLE	450.00	-
1	REAR BONNET TSI EMBLEM	NECESSARY	80.00	80.00
1	REAR BONNET POLO EMBLEM	NECESSARY	88.00	88.00
1	REAR BONNET VW EMBLEM	NECESSARY	85.00	85.00
1	R/L TAILLAMP ASSY	SERVICEABLE	900.00	-
1	R/R TAILLAMP ASSY	SERVICEABLE	900.00	-
1	R/L TAILLAMP RETAINER	SERVICEABLE	130.00	-
1	R/R TAILLAMP RETAINER	SERVICEABLE	130.00	-
1	REAR END PANEL	SERVICEABLE	2,000.00	-
1	REAR END PANEL TOP TRAY GARNISH	SERVICEABLE	350.00	-
1	REAR BONNET LOCK	SERVICEABLE	650.00	-
1	REAR BONNET LOCK CATCH	SERVICEABLE	250.00	-
1	REAR BUMPER	CRUSHED	3,000.00	933.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	1,500.00	-
1	REAR BUMPER LH BRACKET	SERVICEABLE	150.00	-
1	REAR BUMPER RH BRACKET	SERVICEABLE	150.00	-
1	REAR BUMPER LH REFLECTOR	SERVICEABLE	250.00	-
1	REAR BUMPER RH REFLECTOR	SERVICEABLE	250.00	-
1	REAR EXHAUST SILENCER	SERVICEABLE	1,500.00	-
	LESS 10% DISCOUNT		-	-118.60
			15,813.00	1,067.40
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	SHORTED	480.00	200.00
1	BUMPER CLIPS (SN)	NECESSARY	200.00	30.00
			680.00	230.00

Report Ref No. CS1/LPC20007165/Qyf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO LABOUR CHARGE FOR CUTTING OUT, REMOVING REAR BUMPER AND END PANEL TO FACILITATE REPLACEMENT OF DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BONNET. TO RESPRAY REAR BONNET, END PANEL, SPARE TYRE PANEL AND REAR BUMPER. TO REMOVE AND INSTALL UPHOLSTERY AND REAR SEAT OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.		3,000.00 2,000.00 400.00 5,400.00	400.00 400.00 30.00 830.00
GRAND TOTAL			21,893.00	2,127.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CS1/LPC20007165/Qyf3s2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.