

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20007171/AKS3Q2
Date: 23/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993796
Claimant Vehicle No :	SMT1806B	Insured Vehicle No :	SLR7189G
Date of Loss:	09/07/2020	Nature of Claim:	TP
		Claim No:	1622422817SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT1806B		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD891683
Reg. Date:	30/03/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF37L1078502
Colour:	White	Odometer:	2941 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,110.00	0.00	1,110.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,672.00	0.00	4,672.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,782.00	0.00	5,782.00	100.00
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 16/07/2020

Date Inspected: 16/07/2020

Estimated Period of Repair: 0.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT WHEEL COVER -LH/RH (O/S CUT / N/S NECESSARY)	Not Consistent With The Impact	1,010.00 FS	*- FS
2	1		*SUNDRIES (NOT NECESSARY)	Not Consistent With The Impact	100.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	1,110.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER /REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM	New	280.00	0.00
2	TO DISMANTLE AND REINSTALL FRONT BUMPER REORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	0.00
3	TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER AND BOTH WHEEL ARCH TRIMS	New	3,000.00	0.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	0.00
Gross Labour Cost (S\$)			4,672.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >