

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/III20007175/R1BS3Q2  
**Date:** 08/07/2021

**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	PC2270T	<b>Insured Vehicle No :</b>	SH9545T
Date of Loss:	20/06/2020	Nature of Claim:	TP
		Claim No:	MCT20060224

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>PC2270T</b>	Engine No:	ISBE420522009323
Make & Model:	KING LONG XMQ6902K, 6.7 D (A)	Chassis No:	LA6R1DSB1BB205334
Reg. Date:	11/12/2013 (Man. Year: 2011)	Odometer:	98618 km
Colour:	Multi-colour		
Engine Capacity:	6700 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Double Star 8 mm	Rear Left Side:	Double Star 8/8 mm
Front Right Side:	Double Star 8 mm	Rear Right Side:	Double Star 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,454.80	3,132.90	12,321.90	79.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,950.00	1,940.00	7,010.00	78.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,404.80</b>	<b>5,072.90</b>	<b>19,331.90</b>	<b>79.21</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,050.00</b>		

<b>Nett Amount (S\$)</b>	<b>24,404.80</b>	<b>4,050.00</b>	<b>20,354.80</b>	<b>83.40</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 09/07/2020

Date Inspected: 13/07/2020

Estimated Period of Repair: 6.0 days

Inspected At:

One Line Motorworks Trading (HQ)  
 11 TUAS BAY CLOSE #06-02/06-03 WEST STAR  
 Singapore 636996

**Adjuster:** MOHD RASUL**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 Dec 2020)	
<b>Parts:</b>	N/A	KING LONG XMQ6902K 6.7 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC2270T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER STRUCTURAL FRAME ASSY	Serviceable	1,400.00 FL	*- FL
2	1		*FRONT BUMPER ASSY	Cracked	2,400.00 FL	*1,250.00 FL
3	1		*FRONT CENTRE PANEL ASSY	Cracked	4,600.00 FL	*1,014.00 FL
4	1		*FRONT CENTRE PANEL STRUCTURAL FRAME ASSY	Serviceable	3,600.00 FL	*- FL
5	1		*FRONT LEFT HAND SIDE HEADLAMP	Scratched	960.00 FL	*580.00 FL
6	1		*FRONT LEFT HAND SIDE SPOTLAMP	Scratched	560.00 FL	*97.00 FL
7	1		*FRONT LEFT HAND SIDE EXTREME DOOR OUTER WEATHERSTRIP }	Cut	580.00 FL	*510.00 FL
8	1		*FRONT LEFT HAND SIDE EXTREME DOOR INNER WEATHERSTRIP }	Cut	460.00 FL	*- FL
9	1		*FRONT LEFT HAND SIDE WIPER ARM	Serviceable	840.00 FL	*- FL
10	1		*FRONT LEFT HAND SIDE WIPER BLADE	Serviceable	520.00 FL	*- FL
11	1		*FRONT LEFT HAND SIDE INNER WIPER MOTOR LINKAGE ARM	Serviceable	1,200.00 FL	*- FL
12	1		*FRONT LEFT HAND SIDE WIPER ARM CAP COVER	Scratched	52.00 FL	*30.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>17,172.00</b>	<b>3,481.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,717.20	348.10
<b>Total Parts (\$\$)</b>	<b>15,454.80</b>	<b>3,132.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO SUPPLY AND SPRAY INSULATION FOAM ON ALL AFFECTED PARTS	New	800.00	0.00
2	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT CENTRE PANEL ,FRONT SIDE PANEL AND ALL AFFECTED ACCIDENT PARTS INCLUDING DESIGN PAINTING ON SAME (MULTI COLOR)	New	2,000.00	900.00
3	TO JACK/KNOCK /STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPAIRING AND CHANGING OF ALL DAMAGED PARTS AND ALIGN SAME	New	3,500.00	1,000.00
4	TO CHECK/ADJUST WIRING SYSTEM AND ALIGNMENT OF HEADLAMP	New	150.00	40.00
5	TO REMOVE PANEL ,BUMPER ,WIPER MOTOR /LINKAGE ARM /WIPER ARM /WIPERBLADE AND REFIT NEW	New	2,500.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>8,950.00</b>	<b>1,940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >