Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007193/ADS3Q2

Date: 23/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100273563

Claimant
Vehicle No: GBF3617X

GBF3617X

Insured Vehicle No: SKC6757P

Date of Loss: 30/06/2020 Nature of Claim: TP Claim No: 0824508188SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF3617X

Make & Model: MITSUBISHI L200, 2.4 D DOUBLE CAB (M) Engine No: 4N15UAR5709

Reg. Date: 23/09/2016 (Man. Year: 2016) Chassis No: MMAJYKL10GH024756

Colour: White Odometer: 97186 km

Engine Capacity: 2442 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/70R16 Rear Tyre Size: 245/70R16
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,350.40	1,569.30	781.10	33.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	780.00	2,120.00	73.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,250.40	2,349.30	2,901.10	55.25
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	5,250.40	1,850.00	3,400.40	64.76
+ GST 7.00/7.00% (S\$)	367.53	129.50	238.03	64.76
Nett Amount (S\$)	5,617.93	1,979.50	3,638.43	64.76
+ Loss of Use (3.0 x S\$100.00/day) (S\$) + Doc/Search Fee (S\$)		300.00		
		36.45		
Net	t Liability (S\$)	2,315.95		

INSPECTION

Date of Assignment: 13/07/2020

Date Inspected: 24/07/2020 Inspected At: Dynamic Autowork Pte. Ltd (HQ)

8 Kaki Bukit Ave 4, #08-09 Premier @

Kaki Bukit

Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount			
1	1	*REAR BUMPER	Deformed	652.00 FL	*652.00 FL			
2	1	*REAR BUMPER CENTER STEP GARNISH	Deformed	41.00 FL	*41.00 FL			
3	2	*REAR BUMPER SIDE STEP GARNISH	Deformed	64.00 FL	*64.00 FL			
4	1	*REAR BUMPER BRACKET (INNER)	N/s Bent	178.00 FL	*89.00 FL			
5	1	*REAR BUMPER REINFORCEMENT	Bent	631.00 FL	*631.00 FL			
6	1	*REAR NUMBER PLATE	Not Necessary	80.00 FS	*-FS			
7	1	*SET REAR BUMPER CLIP	Not Necessary	60.00 FS	*-FS			
8	1	*SET REAR BUMPER CENTER STEP GARNISH CLIF	Necessary	40.00 FS	S *20.00 FS			
9	1	*SET REAR BUMPER SIDE STEP GARNISH CLIP	Necessary	40.00 FS	*20.00 FS			
10	1	*REAR END PANEL SEALANT	Not Necessary	150.00 FS	*-FS			
11	1	*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS			
12	1	*REAR END PANEL	Repair	390.00 FL	*- FL			
F=Franchise part. S=SpcNett. L=ListItemDisc.								
			Sub Total (S\$)	2,546.00	1,717.00			
- List Item Discount on L Items 10.00/10.00% (S\$)				195.60	147.70			
			Total Parts (S\$)	2,350.40	1,569.30			
Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PANEL BEAT,WELD,CUT,ADJUST,KNOCK	New	800.00	300.00
2	TO PUTTY,SPRAY PAINT,POLISH WAX	New	800.00	400.00
3	TO SPRAY TUFF COAT	New	250.00	30.00
4	WIRING,BULB CHECKING	New	60.00	0.00
5	REMOVE AND REFIX CARGO BED COVER	New	650.00	0.00
6	REMOVE AND REFIX TAILGATE	New	80.00	0.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
	Gross Labour Cost (S\$)		2,900.00	780.00
	Report was unsubmitted durin	a this print-out		

< END OF ESTIMATES >