

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)
8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Tel : 6341 6789 Fax: 6341 6778
E-mail:dynamicautowork@gmail.com

DATE : 23.07.20

TO : **AIG MOTOR CLAIMS DEPTS**
VEHICLE NO : **GBF3617X**
MODEL : **MIT-L200**
DATE OF ACCIDENT : **30.06.20**
TIME OF ACCIDENT : **16:40HRS**

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Reformed</i>	1	\$ 652.00	\$ 652.00
2	REAR BUMPER CENTER STEP GARNISH <i>Reform</i>	1	\$ 41.00	\$ 41.00
3	REAR BUMPER SIDE STEP GARNISH <i>Reform</i>	2	\$ 32.00	\$ 64.00
4	REAR BUMPER BRACKET (INNER) <i>Left Back</i>	2	\$ 89.00	\$ 178.00 <i>178.00</i>
5	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 631.00	\$ 631.00
6	REAR END PANEL <i>Reps</i>	1	\$ 390.00	\$ 390.00

1477
1319.30
TOTAL PRICE \$ 1,956.00
LESS 10% \$ 195.60
SUB TOTAL PRICE \$ 1,760.40

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Re nu</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIP (SET) <i>Re nu</i>	1	\$ 60.00	\$ 60.00
3	REAR BUMPER CENTER STEP GARNISH CLIP (SET) <i>Re nu</i>	1	\$ 40.00	\$ 40.00
4	REAR BUMPER SIDE STEP GARNISH CLIP (SET) <i>Re nu</i>	1	\$ 40.00	\$ 40.00
5	REAR END PANEL SEALANT <i>Re nu</i>	1	\$ 150.00	\$ 150.00
6	REVERSE SENSOR <i>Dangd</i>	1	\$ 220.00	\$ 220.00

240
TOTAL \$ 590.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 800.00	300
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 800.00	400
3	TO SPRAY TUFF COAT	\$ 250.00	30

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBF3617X**
MODEL : **MIT-L200**
DATE OF ACCIDENT : 30.06.20
TIME OF ACCIDENT : 16:40HRS

4	WIRING, BULB CHECKING	\$ 60.00	X
5	REMOVE AND REFIX CARGO BED COVER	\$ 650.00	X
6	REMOVE AND REFIX TAILGATE	\$ 80.00	X
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 2,900.00

780

ESTIMATE REPORT

TOTAL PARTS COST : \$ 2,350.40
TOTAL LABOUR COST : \$ 2,900.00
TOTAL REPAIR COST : \$ 5,250.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR

ABBY

HP : 9856 4815

Adrian Lj

1/5 24/07/20.

03Days.

total: 234930

1/5: 1250.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: