

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20007194/EVF3E2

Date: 17/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900113245
Claimant Vehicle No : FBN4019Z	Insured Vehicle No : SMM3633G
Date of Loss: 18/10/2019	Nature of Claim: TP Claim No: 7810165716SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN4019Z	Engine No:	G3E6E0423150
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740J0120061
Reg. Date:	20/09/2018 (Man. Year: 2018)	Odometer:	21 km
Colour:	Blue		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90-17	Rear Tyre Size:	90/100-17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	09/07/2020	
Date Inspected:	13/07/2020	Inspected At: Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb Singapore 417800
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cut	0.00 F	*- F
2	1		*FRONT RIM	Cut	0.00 F	*- F
3	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
4	2		*FRONT FORK INNER TUBE	Bent	0.00 F	*- F
5	2		*FRONT FORK OUTER TUBE	Bent	0.00 F	*- F
6	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
7	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
8	1		*FRONT HEADLAMP	Missing	0.00 F	*- F
9	1		*FRONT HEADLAMP BRACKET	Bent	0.00 F	*- F
10	2		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
11	2		*FRONT WING MIRROR	Cut	0.00 F	*- F
12	1		*FRONT LH SIGNAL LAMP	Broken	0.00 F	*- F
13	1		*FRONT RH SIGNAL LAMP	Broken	0.00 F	*- F
14	1		*ERP BRACKET	Bent	0.00 F	*- F
15	1		*ERP UNIT	Cut	0.00 F	*- F
16	1		*STEERING CONE	Necessary	0.00 F	*- F
17	1		*HANDLE BAR	Bent	0.00 F	*- F
18	1		*HANDLE BAR BALANCER LH	Missing	0.00 F	*- F
19	1		*HANDLE BAR BALANCER RH	Missing	0.00 F	*- F
20	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
21	2		*SIDE FAIRING	Cut	0.00 F	*- F
22	1		*FAIRING SHIELD (FRONT)	Cut	0.00 F	*- F
23	3		*CENTER FAIRING	Broken	0.00 F	*- F
24	2		*FAIRING LOWER	Broken	0.00 F	*- F
25	1		*RADIATOR	Bent	0.00 F	*- F
26	1		*RADIATOR FAN MOTOR	Broken	0.00 F	*- F
27	1		*SEAT ASSY	Torn	0.00 F	*- F
28	1		*FOOT BRAKE	Bent	0.00 F	*- F
29	1		*FRONT FOOT REST	Bent	0.00 F	*- F
30	1		*FRONT FOOT REST BRACKET	Bent	0.00 F	*- F
31	2		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
32	1		*EXHAUST MUFFLER ASSY	Dented	0.00 F	*- F
33	1		*REAR BOX	Missing	0.00 F	*- F
34	1		*REAR BOX BRACKET	Bent	0.00 F	*- F
35	1		*EMBLEM	Necessary	0.00 F	*- F
36	1		*STICKER	Necessary	0.00 F	*- F
37	1		*THERMOSTAT SWITCH	Broken	0.00 F	*- F
38	1		*ENGINE CYLINDER HEAD	Broken	0.00 F	*- F
39	1		*ENGINE GASKET	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >