



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. ET 9292A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT RH FENDER UNDERSHIELD	REPLACED	356.00	302.00
1	FRONT RH FENDER	REPAIRED SEE LABOUR	2,254.30	-
1	FRONT RH FENDER SIGNAL LAMP	REPLACED	420.00	130.00
1	FRONT BUMPER RH FOG LAMP	REPLACED	521.30	521.30
	LESS 10% DISCOUNT		-355.16	-95.33
			3,196.44	857.97
<b>SPECIAL NETT ITEMS</b>				
1	FRONT BUMPER ASSY (SN)	REPLACED	16,500.00	6,990.30
1	SET FRONT BUMPER LOWER CARBON FIBER SKIRTING (SN)	REPLACED	6,000.00	4,550.00
1	SET FRONT RH FENDER UNDER SHIELD CLIPS (SN)	REPLACED	40.00	40.00
1	SET FRONT BUMPER & FRONT RH FENDER BODY STICKER (SN)	REPLACED	800.00	400.00
			23,340.00	11,980.30
<b>LABOUR</b>				
	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT RH FENDER.		1,000.00	400.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		1,000.00	400.00
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT TEST.		120.00	60.00
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS.		50.00	30.00
			2,170.00	890.00
<b>GRAND TOTAL</b>			<b>28,706.44</b>	<b>13,728.27</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>10,900.00</b>

Report Ref No. CS3/AIG20004437/Bqf3s2-1

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.