

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD20007203/GQF3E2

Date: 01/12/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00009928-01

Claimant Vehicle No : SMT3016B **Insured Vehicle No :** SLQ8080J

Date of Loss: 09/07/2020 Nature of Claim: TP Claim No: 1202000018920

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT3016B**

Make & Model: TOYOTA CAMRY, 2.5 (A)

Engine No: A25A5316502

Reg. Date: 06/04/2020 (Man. Year: 2019)

Chassis No: JTNB23HKX03056886

Colour: White

Odometer: 4974 km

Engine Capacity: 2487 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18

Rear Tyre Size: 235/45 R18

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,617.39	7,521.70	1,095.69	12.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,680.00	670.00	28.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,967.39	9,201.70	1,765.69	16.10

INSPECTION

Date of Assignment: 13/07/2020

Date Inspected: 13/07/2020 Inspected At:

Auto Soon Pte Ltd (HQ)
BLOCK 176 SIN MING DRIVE, #01-10
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$9,201.69

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2020)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT3016B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE ASSY	Cut	688.30 FL	*653.60 FL
2	1		*BUMPER FACIAL	Cracked	591.30 FL	*591.30 FL
3	10		*BUMPER FACIAL CLIPS	Necessary	50.00 FL	*50.00 FL
4	1		*BUMPER LOWER GRILLE	Not Necessary	763.30 FL	*- FL
5	1		*BUMPER REINFORCEMENT ASSY	Not Necessary	355.30 FL	*- FL
6	1		*O/S BUMPER RETAINER ASSY	Deformed	97.42 FL	*86.60 FL
7	1		*O/S FOG LAMP COVER	Not Necessary	68.30 FL	*- FL
8	1		*O/S PARKING SENSOR ASSY	Damaged	472.10 FL	*380.80 FL
9	1		*O/S PARKING SENSOR BEZEL	Necessary	26.00 FL	*12.00 FL
10	1		*O/S HEAD LAMP ASSY	Cut	2,690.00 FL	*2,690.00 FL
11	1		*O/S FENDER ASSY	Buckled	689.20 FL	*689.20 FL
12	1		*O/S FENDER BADGE	Necessary	39.30 FL	*39.30 FL
13	1		*O/S FENDER INNER SHIELD	Deformed	240.55 FL	*240.55 FL
14	8		*O/S FENDER INNER SHIELD CLIP	Necessary	40.00 FL	*40.00 FL
15	1		*O/S ALLOY WHEEL ASSY	Cut	2,300.00 FL	*2,252.50 FL
16	1		*O/S WHEEL BEARING ASSY	Jammed	139.26 FL	*139.26 FL
17	1		*O/S WHEEL BEARING HUD	Bent	467.80 FL	*467.80 FL
18	1		*O/S WHEEL KNUCKLE ARM	Bent	501.41 FL	*501.41 FL
19	1		*O/S WHEEL LOWER ARM ASSY	Bent	528.80 FL	*528.80 FL
20	1		*O/S WHEEL SHOCK ABSORBER	Bent	548.00 FL	*472.30 FL
21	1		*O/S WHEEL SHOCK ABSORBER TOP MOUNTING	Bent	193.51 FL	*193.51 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,489.85	10,028.93
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,872.46	2,507.23
Total Parts (\$\$)	8,617.39	7,521.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRE AFFECTED SECTION AND REFOCUS HEAD LAMP BEAM	New	50.00	30.00
2	TO COMPUTER CHECK/READJUST WHEEL REALIGNMENT IN REPAIR	New	80.00	60.00
3	TO REPLACE WHEEL CONTROL ARMS, KNUCKLE BEARING AND HUD INCLUDE SHOCK ABSORBER, MOUNTING IN REPAIR	New	180.00	150.00
4	TO PUTTY AND RESPRAY AFFECTED PANELS IN REPAIR	New	1,280.00	900.00
5	TO UNDERSEALING DAMAGED PANELS WITH ANTI RUST	New	80.00	60.00
6	TO REMOVE DAMAGED PORTION, RESTRAIGHTEN/RECONDITION O/S WHEEL HOUSING. PANEL BEAT HEAD LAMP PANEL, SUPPORT PANEL AND ALL AFFECTED DOORS INCLUDE REALIGN BUMPER IN REPAIR	New	680.00	480.00
Gross Labour Cost (\$\$)			2,350.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >