

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007211/QRS3Q2

Date: 24/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100502729
Claimant
Vehicle No : PC6207B **Insured Vehicle No :** SLL5471K
Date of Loss: 01/07/2020 **Nature of Claim:** TP **Claim No:** 7727700389SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC6207B
Make & Model: MITSUBISHI ROSA, 3.0 D BE641JRMDEB (A) **Engine No:** 4P10C62133
Reg. Date: 17/07/2017 (Man. Year: 2017) **Chassis No:** BE641JK30360
Colour: White **Odometer:** 128600 km
Engine Capacity: 2998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 7.00 R16LT **Rear Tyre Size:** 7.00 R16LT
Front Left Side: Headway 6 mm **Rear Left Side:** Headway 6 mm
Front Right Side: Headway 6 mm **Rear Right Side:** Headway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,681.13	1,500.00	15,181.13	91.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,600.00	1,270.00	11,330.00	89.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,281.13	2,770.00	26,511.13	90.54
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	29,281.13	2,450.00	26,831.13	91.63
+ GST 7.00/7.00% (S\$)	2,049.68	171.50	1,878.18	91.63
Nett Amount (S\$)	31,330.81	2,621.50	28,709.31	91.63
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,128.99		
Global Sum Settlement (S\$)		3,100.00		

INSPECTION

Date of Assignment: 09/07/2020
Date Inspected: 14/07/2020 **Inspected At:** SMRT Automotive Services Pte Ltd
 (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	3,000.00 F	*3,000.00 FL
2	1		*REAR BUMPER REVERSE LAMP LH	Not Necessary	350.00 F	*- FL
3	1		*REAR BUMPER REVERSE LAMP RH	Not Necessary	350.00 F	*- FL
4	1		*REAR DOOR PANEL LH	Not Necessary	2,574.00 F	*- FL
5	1		*REAR DOOR PANEL RH	Not Necessary	2,574.00 F	*- FL
6	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
7	2		*REAR LICENCE PLATE LAMP	Not Necessary	370.00 F	*- FL
8	1		*REAR DOOR PANEL LH HINGE UPPER	Not Necessary	225.00 F	*- FL
9	1		*REAR DOOR PANEL LH HINGE LOWER	Not Necessary	225.00 F	*- FL
10	1		*REAR DOOR PANEL RH HINGE UPPER	Not Necessary	225.00 F	*- FL
11	1		*REAR DOOR PANEL RH HINGE LOWER	Not Necessary	225.00 F	*- FL
12	1		*REAR PILLAR PANEL RH	Repair	1,200.00 F	*- FL
13	1		*REAR PILLAR PANEL LH	Not Necessary	1,200.00 F	*- FL
14	1		*RHS SIGNAL LAMP	Not Necessary	155.00 F	*- FL
15	1		*REAR SIGNAL LAMP LH	Not Necessary	455.20 F	*- FL
16	1		*REAR SIGNAL LAMP RH	Not Necessary	455.20 F	*- FL
17	1		*REAR BRAKE LAMP LH	Not Necessary	455.20 F	*- FL
18	1		*REAR BRAKE LAMP RH	Not Necessary	455.20 F	*- FL
19	1		*REAR BUMPER TOWING COVER	Not Necessary	190.00 F	*- FL
20	1		*LH DOOR HANDLE	Not Necessary	322.33 F	*- FL
21	1		*STICKER EMERGENCY DOOR PULL TO OPEN	Not Necessary	150.00 FS	*- FS
22	1		*REAR END PANEL	Not Necessary	1,500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,681.13	3,000.00
- List Item Discount on L Items 0.00/50.00% (\$\$)	0.00	1,500.00
Total Parts (\$\$)	16,681.13	1,500.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE LABOUR TO PANEL BEATING RHS BODY PANEL, REMOVE USED STICKER RESIDE AND REPASTE STICKER ADVERTISEMENT, REMOVE AND REFIT REPLACEMENT PARTS.	New	3,000.00	400.00
2	TO RESPRAY REAR BUMPER.	New	800.00	250.00
3	TO RESPRAY REAR DOOR PANEL LH.	New	800.00	0.00
4	TO RESPRAY REAR DOOR PANEL RH.	New	800.00	0.00
5	TO RESPRAY PAINT REAR END PANEL.	New	400.00	0.00
6	TO RESPRAY PAINT REAR PILLAR PANEL RH.	New	400.00	250.00
7	TO RESPRAY PAINT REAR PILLAR PANEL LH.	New	400.00	0.00
8	TO PROVIDE ANTI RUST COATING ON ACCIDENT AREA.	New	500.00	50.00
9	TO CHECK WIRING SYSTEM AND FUNCTION.	New	300.00	20.00
10	TO TRANSFER DOOR MECHANISM.	New	700.00	0.00
11	TO REMOVE AND REFIT REAR GLASS LH AND RH.	New	700.00	0.00
12	TO WASH AND VACUUM.	New	100.00	0.00
13	TO REPLACE AND SUNDRY PARTS.	New	300.00	0.00
14	TO TEST ALL MECHANISM, WATER LEAKAGE AND ALL LUGGAGE COMPARTMENT.	New	400.00	0.00
15	TO PROVIDE ADVERTISEMENT STICKER.	New	3,000.00	300.00
Gross Labour Cost (\$\$)			12,600.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >