

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 9637M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE GATE RH	TO REPAIR SEE LABOUR	1,245.80	-
4	SIDE GATE HINGE @\$35.00	DAMAGED (2PCS ONLY)	140.00	70.00
1	TAIL GATE STOPPER RH	BENT	210.50	210.50
1	SIDE GATE LOWER PLATFORM END PANEL	TO REPAIR SEE LABOUR	512.50	-
1	REAR MUDGUARD RH	TO REPAIR SEE LABOUR	112.40	-
	LESS 25% DISCOUNT		-555.30	-70.13
			1,665.90	210.37
	<u>LABOUR</u>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF SIDE GATE RH, SIDE GATE LOWER PLATFORM END PANEL AND REAR MUDGUARD RH.		630.00	300.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		400.00	400.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.	NOT NECESSARY	30.00	-
	WIRING AND BULB CHECKING.	NOT NECESSARY	22.50	-
			1,082.50	700.00
	GRAND TOTAL		2,748.40	910.37
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			700.00

Report Ref No. CS3/III20004343/R1tf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.