

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20007213/ATF3Q2

**Date:** 04/11/2020

### REFERENCE

Insured/Claimant:	CHEE HELEN	Policy No:	2100454920-04	
Date of Loss:	09/07/2020	Nature of Claim:	OD	Claim No: 5524389652SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFY230A		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN002774
Reg. Date:	29/02/2016 (Man. Year: 2015)	Chassis No:	WAUZZZF4XGA027770
Colour:	White	Odometer:	37925 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,545.72	9,783.28	6,762.44	40.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,252.00	3,122.00	5,130.00	62.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,797.72</b>	<b>12,905.28</b>	<b>11,892.44</b>	<b>47.96</b>
<b>- Excess (S\$)</b>	<b>1,600.00</b>	<b>1,600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>23,197.72</b>	<b>11,305.28</b>	<b>11,892.44</b>	<b>51.27</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,623.84</b>	<b>791.37</b>	<b>832.47</b>	<b>51.27</b>
<b>Nett Amount (S\$)</b>	<b>24,821.56</b>	<b>12,096.65</b>	<b>12,724.91</b>	<b>51.27</b>

### INSPECTION

Date of Assignment: 13/07/2020

Date Inspected: 13/07/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,010.00 FS	*1,608.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	269.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Damaged	67.00 FS	*55.68 FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	198.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE-LH	Cracked	59.00 FS	*49.52 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	344.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION-LH	Damaged	34.00 FS	*27.12 FS
8	1		*FRONT FENDER-LH	Distorted	722.00 FS	*577.60 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
10	1		*FRONT FENDER CLOSING ELEMENT-LH	Damaged	47.00 FS	*39.20 FS
11	1		*FRONT FENDER BRACKET-LH	Bent	33.00 FS	*26.24 FS
12	1		*DEFORMATION ELEMENT BRACKET-LH	Bent	46.00 FS	*38.80 FS
13	1		*FRONT FENDER BRACKET	Bent	32.00 FS	*24.96 FS
14	1		*FRONT FENDER BRACE	Bent	112.00 FS	*93.60 FS
15	1		*FRONT FENDER CLOSING ELEMENT-LH	Not Necessary	31.00 FS	*- FS
16	1		*WHEEL HOUSING LINER-LH	Torn	226.00 FS	*180.40 FS
17	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	86.00 FS	*- FS
18	1		*WHEEL SPOILER	Cracked	69.00 FS	*57.76 FS
19	1		*WHEEL SPOILER TRIM-LH	Not Necessary	33.00 FS	*- FS
20	1		*STONE CHIP GUARD	Necessary	48.00 FS	*37.92 FS
21	1		*FENDER LEDGE COVER-UPPER	Deformed	29.00 FS	*23.20 FS
22	1		*FENDER LEDGE COVER-LOWER	Missing	21.00 FS	*16.72 FS
23	1		*BONNET	Not Necessary	2,634.00 FS	*- FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	116.00 FS	*- FS
25	3		*BONNET IMPACT PROTECTION-LH/RH/CENTRE	Not Necessary	78.00 FS	*- FS
26	1		*LED HEADLIGHT-LH	Cut	7,321.00 FS	*5,856.80 FS
27	1		*LIFT CYLINDER-LH	Not Necessary	198.00 FS	*- FS
28	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	88.00 FS	*- FS
29	1		*FRONT ALUMINIUM RIM-LH	Cut	660.00 FS	*527.60 FS
30	1		*SUNDRIES	Necessary	300.00 FS	*97.44 FS
31	1		*AIRCON REFRIGERANT PIPE	Bent	413.20 FS	*413.20 FS
32	1		*COMPENSATING PIECE FOR HEADLAMP	Bent	31.52 FS	*31.52 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 16,545.72 9,783.28**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO TOW IN VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.TO CARRY OUT CALIBRATION	New	350.00	250.00
3	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	350.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND BONNET.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
5	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS FRONT DOOR	New	3,700.00	1,100.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REMOVE AND RENEW AIRCOND REFRIGERANT PIPE. (FRONT AIRCOND COMPRESSOR AND AIRCON CONDENSER TO CUT OFF POINT) VACUUM AND REGAS	New	300.00	300.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,252.00</b>	<b>3,122.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >