



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 7989X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	CARGO BOX PILLAR REAR RH	TO REPAIR SEE LABOUR	1,520.00	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	1,422.00	-
			2,942.00	-
	<u>LABOUR</u>			
	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN DOOR PILLAR. REPAIR, RESHAPE DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS. INCLUSIVE OF THE REPAIR OF CARGO BOX PILLAR REAR RH AND DOOR PANEL REAR RH.		1,000.00	400.00
	TO SPRAY PAINT REPLACED / REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		400.00	400.00
			1,400.00	800.00
	GRAND TOTAL		4,342.00	800.00
RECOMMENDED COST OF REPAIRS				800.00

Report Ref No. CC4/FCI20007219/Qks3s2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.