

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD INV No. AC2103110

36 ROBINSON ROAD INV Date 04/05/2021

#16-01 CITY HOUSE Reference CC4/FCI20007222/Kgs3q2

SINGAPORE 068877 Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SGL 3689Y

Insured Veh. SHA 3260X

Claim No. D20002727MFSH

Policy No. D-20094922MFSH

Accident Date 07/07/2020

Inspection Date 13/07/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile						
	MS FIRST CAPITA	AL INSURANCE LTD	Ref:	CC4/FCI20007222/Kgs3q2			
	36 ROBINSON RC #16-01 CITY HOUS	OAD SESINGAPORE 068877	Date:	04/05/2021			
			Code	: FCI2			
1.	Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SHA 3260X	Veh. Inspected	SGL 3689Y			
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00			
	Claim No.	D20002727MFSH	Excess (\$)	0.00			
	Assign From	VIC	Assign Date	13/07/2020			
2.		Vehicle Partic	culars & Condition				
	Make & Model	HONDA JAZZ (A)	c.c	1497			
	Engine No.	HIDDEN	Year of Reg.	2009			
	Chassis No.	JHMGE88509S201711	Colour	METALLIC GREY			
	Odometer	135044 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3.		Conditi	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	205/55 R16	YOKOHAMA	4 mm			
	L/H Front Tyre	205/55 R16	YOKOHAMA	4 mm			
	R/H Rear Tyre	205/55 R16	YOKOHAMA	4 mm			
	L/H Rear Tyre	205/55 R16	YOKOHAMA	4 mm			
4.		Description	on of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.						
	DAMAGES SEE D	ETAILS.					
5.		Genera	I Information				
	Accident Date	07/07/2020	Inspection Date	13/07/2020			
	Survey held at	CITY AUTO PTE LTD					
		BLK 8, SIN MING IND. ESTATE					
		#01-60/62 Sector C					
		SINGAPORE 575643.					
5a.			emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.		Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days						



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGL 3689Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BENT	771.50	771.50
1	TAILGATE GLASS MOULDING	NECESSARY	36.80	36.80
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	189.00	-
1	TAILGATE STRIKER	SERVICEABLE	37.50	-
2	TAILGATE DAMPER @\$136.20	SERVICEABLE	272.40	-
2	TAILGATE STOPPER @\$22.00	SERVICEABLE	44.00	-
1	TAILGATE EMBLEM -JAZZ	NECESSARY	32.20	32.20
1	REAR BUMPER	BENT	460.30	460.30
2	REAR BUMPER RETAINER @\$18.50	DISTORTED	37.00	37.00
1	REAR BUMPER LOWER COVER	BUCKLED	145.00	145.00
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
2	TAIL LAMP @\$226.20	SERVICEABLE	452.40	-
2	TAILLAMP CLIP @\$4.50	NOT NECESSARY	9.00	-
1	REAR END PANEL	BENT	296.50	296.50
1	REAR END PANEL TOP GARNISH	MTG DISTORTED	60.80	60.80
1	REAR FLOOR DECK FOAM	SERVICEABLE	114.60	-
2	REAR FENDER TRIM @\$203.20	SERVICEABLE	406.40	-
1	TRUNK FLOOR PANEL	TO REPAIR SEE LABOUR	737.00	-
	LESS 20% DISCOUNT		-828.28	-375.82
			3,313.12	1,503.28
1	TAILGATE WEATHERSTRIP (50%) (SN)	TWISTED	92.30	46.15
	LESS 20% DISCOUNT		-18.46	-
			73.84	46.15
	SPECIAL NETT ITEMS			
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
			290.00	40.00

Report Ref No. CC4/FCI20007222/Kgs3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,350.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS .		100.00	100.00
	TO REMOVE AND REFIT TRIMS AND UPHOLSTERY .		120.00	60.00
	TO CHECK WIRING AND LIGHTING .		45.00	15.00
	TO SUPPLY PANEL SEALANT AND TO SEAL OFF ALL WELD SPOT SEAM AND GAPS.		80.00	30.00
	TO SPRAY RUBBERIZED UNDER-COATING.		60.00	60.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK AND TRUNK FLOOR PANEL .		1,000.00	500.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		1,200.00	600.00
			2,605.00	1,365.00
	GRAND TOTAL		6,281.96	2,954.43

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

Report Ref No. CC4/FCI20007222/Kgs3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGL 3689Y

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGL 3689Y

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGL 3689Y

RE-INSPECTION



