

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20007227/KGS3Q2

**Date:** 15/10/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015		
<b>Claimant</b>				
<b>Vehicle No :</b> SKR1353A	<b>Insured Vehicle No :</b>	SHD3364P		
Date of Loss: 09/07/2020	Nature of Claim:	TP	Claim No:	MCT20070122

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKR1353A</b>			
Make & Model:	MERCEDES-BENZ B180, 1.6 (R16 BI) (A)	Engine No:	27091030510960	
Reg. Date:	20/01/2015 (Man. Year: 2014)	Chassis No:	WDD2462422J289599	
Colour:	Metallic Grey	Odometer:	68538 km	
Engine Capacity:	1595 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	255/35 R18	Rear Tyre Size:	255/35 R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,343.10	5,876.73	8,466.37	59.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,340.00	1,490.00	2,850.00	65.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,683.10</b>	<b>7,366.73</b>	<b>11,316.37</b>	<b>60.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,850.00</b>		
(S\$)	18,683.10	5,850.00	12,833.10	68.69
<b>+ GST 7.00/7.00% (S\$)</b>	1,307.82	409.50	898.32	68.69
<b>Nett Amount (S\$)</b>	<b>19,990.92</b>	<b>6,259.50</b>	<b>13,731.42</b>	<b>68.69</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>6,988.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>6,950.00</b>		

#### INSPECTION

Date of Assignment:	13/07/2020	
Date Inspected:	14/07/2020 Inspected At:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY Singapore 575722

Estimated Period of Repair: 5.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2020)
<b>Parts:</b> 144	MERCEDES-BENZ B180 1.6 (R16 BI) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKR1353A)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Bent	1,940.20 F	*1,930.00 FL
2	1		*FRONT DOOR GLASS CHANNEL -RH	Serviceable	182.10 F	*- FL
3	1		*FRONT DOOR CHECKER -RH	Serviceable	238.10 F	*- FL
4	1		*FRONT DOOR HINGE LOWER -RH	Repair	198.10 F	*- FL
5	1		*FRONT DOOR HINGE UP-RH	Repair	198.10 F	*- FL
6	1		*FRONT DOOR HINGE LOCK-RH	Repair	655.00 F	*- FL
7	1		*FRONT DOOR OUTER MOULDING -RH	Serviceable	388.00 F	*- FL
8	1		*FRONT DOOR REGULATOR GEAR -RH	Distorted	630.00 F	*420.00 FL
9	1		*FRONT DOOR REGULATOR GEAR MOTOR -RH	Jammed	704.00 F	*704.00 FL
10	10		*FRONT DOOR RIVETS	Necessary	100.00 F	*100.00 FL
11	1		*FRONT DOOR STRIKER -RH	Necessary	108.10 F	*108.10 FL
12	1		*FRONT DOOR TRIM BOARD -RH	Serviceable	1,380.80 F	*- FL
13	1		*FRONT DOOR WEATHERSTRIP -RH (50%)	Necessary	288.00 FS	*144.00 FS
14	1		*REAR DOOR -RH	Bent	1,880.50 F	*1,801.00 FL
15	1		*REAR DOOR CHANNEL-RH	Serviceable	182.10 F	*- FL
16	1		*REAR DOOR CHECKER-RH	Serviceable	238.10 F	*- FL
17	1		*REAR DOOR HINGE LOWER -RH	Repair	198.10 F	*- FL
18	1		*REAR DOOR HINGE UP -RH	Repair	198.10 F	*- FL
19	1		*REAR DOOR LOCK -RH	Repair	655.00 F	*- FL
20	1		*REAR DOOR OUTER MOULDING -RH	Serviceable	90.00 F	*- FL
21	1		*REAR DOOR REGULATOR GEAR-RH	Serviceable	568.00 F	*- FL
22	1		*REAR DOOR REGULATOR GEAR MOTOR-RH	Serviceable	608.00 F	*- FL
23	10		*REAR DOOR RIVETS	Necessary	100.00 F	*100.00 FL
24	1		*REAR DOOR TRIM BOARD	Serviceable	1,280.10 F	*- FL
25	1		*REAR DOOR STRIKER -RH	Necessary	98.10 F	*98.10 FL
26	1		*REAR DOOR WEATHERSTRIP -RH (50%)	Necessary	288.00 FS	*144.00 FS
27	1		*ROCKER PANEL GARNISH -RH	Mtg Cracked	868.50 F	*868.50 FL
28	8		*ROCKER PANEL GARNISH CLIP	Necessary	80.00 F	*80.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,343.10</b>	<b>6,497.70</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	620.97
<b>Total Parts (\$\$)</b>	<b>14,343.10</b>	<b>5,876.73</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS PANEL HEAT WHERE NECESSARY	New	1,800.00	550.00
2	TO PUTTY APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,800.00	800.00
3	TO REMOVE 2 PCS DOOR COMPONENTS	New	160.00	120.00
4	WHEEL ALIGNMENT	New	150.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	80.00	20.00
6	COMPUTER DIAGNOSTIC RESET	New	350.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,340.00</b>	<b>1,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >