



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2100416

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 19/01/2021
Reference CC4/FCI20007231/Ugs3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJR 3536M
Insured Veh. SH 7618E
Claim No. D20002752MFSH
Policy No. D-20094922MFSH
Accident Date 09/07/2020
Inspection Date 14/07/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20007231/Ugs3q2	
			Date: 19/01/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 7618E	Veh. Inspected	SJR 3536M
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00
	Claim No.	D20002752MFSH	Excess (\$)	0.00
	Assign From	RACHELWU	Assign Date	13/07/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER (A)	c.c	1986
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	ZSU600073338	Colour	BLACK
	Odometer	84763 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	205/55 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	205/55 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	205/55 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND ROOFTOP. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/07/2020	Inspection Date	14/07/2020
	Survey held at	ABWIN SERVICE PTE LTD 17 KAKI BUKIT ROAD 4 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 3536M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	1,601.95	881.50
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	69.70	-
1	REAR BUMPER SIDE RETAINER LH	BENT	69.70	69.70
1	REAR BUMPER LOWER GARNISH	DISTORTED	420.69	420.69
1	REAR BUMPER SPONGE	TORN	137.80	137.80
1	REAR END PANEL	DENTED	821.30	821.30
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	421.47	-
1	TAILGATE	DENTED / BENT	1,621.90	1,621.90
1	TAIL GATE EMBLEM	NOT NECESSARY	65.80	-
1	TAIL GATE EMBLEM "HARRIER"	NECESSARY	76.85	76.85
1	TAIL GATE INNER TRIM	NOT NECESSARY	661.75	-
1	TAIL GATE OUTER GARNISH	NOT NECESSARY	1,312.75	-
1	TAIL GATE INNER LOCK	NOT NECESSARY	1,016.40	-
1	TAIL GATE LOCK SENSOR	NOT NECESSARY	136.40	-
1	REAR SMART BUZZER	NOT NECESSARY	150.33	-
1	TAIL GATE WEATHERSTRIP	TWISTED	373.36	373.36
3	REAR WINDSCREEN MOULDING	NECESSARY	225.06	225.06
	LESS 25% DISCOUNT		-	-1,157.04
			9,183.21	3,471.12
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	30.00
1	REAR WINDSCREEN PRIMER & CLEANER (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
10	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
10	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	NUMBER PLATE W/CASING (SN)	NOT NECESSARY	60.00	-
2	REVERSE SENSOR (SN)	SHORTED	600.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	380.00	-
			1,340.00	370.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS.		1,000.00	600.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,200.00	700.00
	TO CHECK WIRING.		150.00	20.00
	TO APPLY UNDERCOATING FOR RUST PROOFING.		150.00	60.00
	TO DISMANTLE AND REPLACE REAR WINDSCREEN COMPONENTS.		150.00	120.00
	TO DISMANTLE,REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING. }		120.00	50.00
	TO DISMANTLE,REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING. }		120.00	-
	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY.		180.00	60.00
	TO DISMANTLE,REPLACE AND/OR REPAIR TAILGATE COMPONENTS.		250.00	60.00
			3,320.00	1,670.00
GRAND TOTAL			13,843.21	5,511.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00

Report Ref No. CC4/FCI20007231/Ugs3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJR 3536M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJR 3536M

RE-INSPECTION

