

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20007233/KPA3Q2  
**Date:** 14/01/2021

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800012071  
**Claimant**  
**Vehicle No :** SJJ3065Y **Insured Vehicle No :** EQ699K  
 Date of Loss: 09/07/2020 Nature of Claim: TP Claim No: 1026031953SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ3065Y**  
 Make & Model: HONDA STREAM, 1.8 X (A) Engine No: R18A1792020  
 Reg. Date: 08/09/2008 (Man. Year: 2008) Chassis No: RN61082892  
 Colour: Metallic Black Odometer: 152513 km  
 Engine Capacity: 1799 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,398.32	3,398.32	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,830.00	270.00	12.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,498.32</b>	<b>5,228.32</b>	<b>270.00</b>	<b>4.91</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,150.00</b>		
<b>(S\$)</b>	5,498.32	4,150.00	1,348.32	24.52
<b>+ GST 7.00/7.00% (S\$)</b>	384.88	290.50	94.38	24.52
<b>Nett Amount (S\$)</b>	<b>5,883.20</b>	<b>4,440.50</b>	<b>1,442.70</b>	<b>24.52</b>
<b>+ Car Rental (6.0 x S\$85.00/day + 7.00% GST) (S\$)</b>		545.70		
<b>+ Doc/Search Fee (S\$)</b>		8.00		
<b>Nett Liability (S\$)</b>		<b>4,994.20</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,990.00</b>		

#### INSPECTION

Date of Assignment: 13/07/2020  
 Date Inspected: 17/07/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
 Blk 1019 #01-374/382, Yishun  
 Industrial Park A  
 Singapore 768761  
 Estimated Period of Repair: 6.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Bent / Cracked	793.10 FL	*793.10 FL
2	1		*FRT BUMPER REINFORCEMENT	Bent	218.50 FL	*218.50 FL
3	1		*FRT BUMPER LH SIDE RETAINER	Cracked	19.80 FL	*19.80 FL
4	6		*FRT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*FRT BUMPER LH FOG LAMP GARNISH	Dented	22.80 FL	*22.80 FL
6	1		*FRT LH FENDER	Bent	539.20 FL	*539.20 FL
7	1		*FRT LH FENDER INNER SHIELD	Cracked	118.90 FL	*118.90 FL
8	6		*FRT LH FENDER INNER SHIELD CLIPS	Necessary	21.00 FL	*21.00 FL
9	1		*LH HEADLAMP HID	Buckled	927.10 FL	*927.10 FL
10	1		*LH HEADLAMP LOWER RETAINER	Cracked	36.50 FL	*36.50 FL
11	1		*FRT GRILLE	Mtg Cracked	289.10 FL	*289.10 FL
12	4		*FRT GRILLE CLIPS	Necessary	14.00 FL	*14.00 FL
13	1		*AIR FILTER RESONATOR	Dented	198.90 FL	*198.90 FL
14	1		*FRT LH FENDER INNER PANEL	Bent	389.10 FL	*389.10 FL
15	1		*BONNET	Bent	638.90 FL	*638.90 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,247.90</b>	<b>4,247.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	849.58	849.58
<b>Total Parts (\$)</b>	<b>3,398.32</b>	<b>3,398.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS ,FRT GRILLE ,FRT FENDERS ,BONNET & ATTACHMENT,KNOCK & REPAIR FRT SUPPORT PANEL ,CUT ,WELD,RENEW FRT LH FENDER INNER PANEL & REALIGN THE SAME	New	800.00	650.00
2	PUTTY & RESPRAY FRT LH DOOR ,FRT BUMPER ,REINFORCEMENT ,SUPPORT PANEL ,FRT LH FENDER ,FRT LH FENDER INNER PANEL ,BONNET	New	1,100.00	1,000.00
3	REMOVE & REFIX FRT LH SPORT RIM,REPAIR ,SPRAY AND BALANCING	New	80.00	60.00
4	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
5	RUSTPROOFING	New	60.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,100.00</b>	<b>1,830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >