

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007241/DRA3Q2
Date: 16/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800146541
Claimant Vehicle No :	SH8871H	Insured Vehicle No :	SMG1714B
Date of Loss:	09/07/2020	Nature of Claim:	TP
		Claim No:	6850021020SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8871H		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRS055101
Reg. Date:	29/06/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU903560936
Colour:	Blue	Odometer:	429362 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,559.38	12,286.19	15,273.19	55.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	1,830.00	3,150.00	63.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	32,539.38	14,116.19	18,423.19	56.62
+ GST 7.00/7.00% (S\$)	2,277.76	988.13	1,289.63	56.62

Nett Amount (S\$)	34,817.14	15,104.32	19,712.82	56.62
+ Loss of Use (9.0 x S\$50.00/day) (S\$)		450.00		
+ Car Rental (9.0 x S\$125.40/day) (S\$)		1,128.60		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		16,770.37		
Global Sum Settlement (S\$)		16,900.00		

INSPECTION

Date of Assignment: 13/07/2020

Date Inspected: 13/07/2020

Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming Industrial Estate

Singapore 575644

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	950.50 FL	*950.50 FL
2	1		*INSULATOR ,HOOD	Not Necessary	398.10 FL	*- FL
3	1		*INSULATOR CLIPS	Not Necessary	3.60 FL	*- FL
4	1		*BONNET RUBBER	Not Necessary	35.50 FL	*- FL
5	1		*BONNET CABLE	Not Necessary	83.20 FL	*- FL
6	1		*BONNET HINGE (RH)	Bent	87.70 FL	*87.70 FL
7	1		*FRONT BUMPER COVER	Torn	499.90 FL	*499.90 FL
8	1		*LAMP ASSY ,FOG, RH	Scratched / Mtg Broken	920.00 FL	*920.00 FL
9	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
10	1		*FRONT BUMPER SIDE RETAINER (O/S)	Broken	77.00 FL	*77.00 FL
11	1		*FRONT LOWER CROSSMEMBER	Not Necessary	357.70 FL	*- FL
12	1		*FRONT UNDER COVER	Not Necessary	180.80 FL	*- FL
13	1		*FRONT BUMPER TOP GARNISH	Not Necessary	225.40 FL	*- FL
14	1		*COVER ,FRONT BUMPER HOLE ,RH	Not Necessary	28.38 FL	*- FL
15	1		*ABSORBER ,FRONT BUMPER ,LOWER	Not Necessary	127.70 FL	*- FL
16	1		*RADIATOR ASSY	Not Necessary	1,841.80 FL	*- FL
17	1		*COOLANT	Not Necessary	45.00 FL	*- FL
18	1		*CONDENSER ASSY ,W/RECEIVER	Not Necessary	1,336.60 FL	*- FL
19	1		*WIRING FRONT	Not Necessary	8,450.50 FL	*- FL
20	1		*UNIT ASSY ,HEADLAMP ,RH (LED)	Mtg Broken	3,455.00 FL	*3,455.00 FL
21	1		*HEADLAMP ECU	Not Necessary	682.60 FL	*- FL
22	1		*HEAD LAMP PANEL (RH)	Bent	240.10 FL	*240.10 FL
23	1		*TOP PANEL SIDE	Bent	145.90 FL	*145.90 FL
24	1		*RADIATOR SPARE TANK HYBRID	Not Necessary	125.80 FL	*- FL
25	1		*WIPER SPARE TANK ASSY	Deformed / Broken	486.70 FL	*486.70 FL
26	1		*WIPER TANK NECK	Not Necessary	89.40 FL	*- FL
27	1		*FENDER SUB-ASSY, FRONT RH	Dented	945.30 FL	*945.30 FL
28	1		*FRONT FENDER SHIELD	Serviceable	198.50 FL	*- FL
29	1		*FRONT FENDER SHIELD CLIP	Not Necessary	14.90 FL	*- FL
30	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	86.50 FL	*86.50 FL
31	1		*FRONT WHEEL RIM	Cut	1,570.55 FL	*1,570.55 FL
32	1		*FRONT WHEEL HUB CAP	Not fitted	175.80 FL	*- FL
33	1		*FRONT WHEEL HUB BEARING	Damaged	559.94 FL	*559.94 FL
34	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	631.90 FL	*631.90 FL
35	1		*FRONT SHOCK ABSORBER (RH)	Distorted	398.20 FL	*398.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*ABSORBER TOP MOUNTING	Not Necessary	196.20 FL	*- FL
37	1		*RACK & PINION ASSY	Not Necessary	1,621.30 FL	*- FL
38	1		*BAR ,STABILIZER	Not Necessary	352.40 FL	*- FL
39	1		*KNUCKLE ,STEERING ,RH	Distorted	580.80 FL	*580.80 FL
40	1		*JOINT ASSY ,LOWER BALL ,FRONT (RH)	Not Necessary	199.98 FL	*- FL
41	1		*DISC ,FRONT	Not Necessary	420.67 FL	*- FL
42	1		*END SUB-ASSY ,TIE ROD ,RH	Not Necessary	159.30 FL	*- FL
43	1		*SENSOR ,SPEED ,FRONT RH	Not Necessary	446.50 FL	*- FL
44	1		*FRONT TYRE (RH)	Serviceable	216.00 FS	*- FS
45	1		*FRONT BUMPER REINFORCEMENT	Bent	696.40 FL	*696.40 FL
46	1		*UNIT ASSY ,HEADLAMP LH (LED)	Mtg Broken	3,455.00 FL	*3,455.00 FL
47	1		*RADIATOR SPARE TANK	Mtg Broken	385.80 FL	*385.80 FL
48	1		*FRONT WINDSCREEN SIDE GARNISH	Dislodged	186.40 FL	*186.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	34,395.22	16,381.59
- List Item Discount on L Items 20.00/25.00% (S\$)	6,835.84	4,095.40
Total Parts (S\$)	27,559.38	12,286.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	800.00
2	SPRAY PAINTING CHARGE	New	1,200.00	600.00
3	WIRING CHARGE	New	140.00	30.00
4	TUFF KOTE	New	120.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	60.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
8	RE-SET FRT ABS SYSTEM	New	200.00	0.00
9	REMOVE/REFIX RADIATOR	New	90.00	0.00
10	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
11	REMOVE/REFIX DASHBOARD	New	350.00	0.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (S\$)			4,980.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >