

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20007242/QTF3E2

Date: 22/09/2020

REFERENCE

Insured/Claimant: ABDUL FARHAN S/O
NAJIRMUNTHEEN

Policy No: DMPCSN30807419000

Date of Loss: 09/07/2020

Nature of
Claim: OD

Claim
No: SNM20D202403/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU6000H**

Make & Model: BMW 520D, 2.0 SE Auto (A)

Engine No: 73019971B47D20A

Reg. Date: 09/11/2017 (Man. Year: 2017)

Chassis No: WBAJC32020G867981

Colour: Blue

Odometer: 72553 km

Engine Capacity: 1995 cc

Market Value/New Car Price: S\$158,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,803.10	4,250.63	9,552.47	69.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,010.00	2,590.00	71.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,403.10	5,260.63	12,142.47	69.77
+ GST 7.00/7.00% (S\$)	1,218.22	368.24	849.98	69.77
Nett Amount (S\$)	18,621.32	5,628.87	12,992.45	69.77

INSPECTION

Date of Assignment: 13/07/2020

Date Inspected: 15/07/2020 Inspected At:

Elite Automotive Pte Ltd (HQ)
280 Woodlands Industrial Park E5, #01-17,
Harvest@Woodlands
Singapore 757322

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2020)
Parts:	143	BMW 520D 2.0 SE Auto (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU6000H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Serviceable	2,947.27 F	*- F
2	1		*FRONT LHS FENDER (WCP)	Repair	1,067.46 F	*- F
3	1		*FRONT BUMPER (WCP)	Dented	1,596.32 F	*850.00 F
4	10		*FRONT BUMPER CLIPS (WCP)	Necessary	80.00 F	*10.20 F
5	1		*FRONT BUMPER RETAINER LHS (WCP)	Broken	57.73 F	*14.00 F
6	1		*FRONT GRILLE LHS (WCP)	Serviceable	243.83 F	*- F
7	1		*LHS HEADLAMP (WCP)	Crumpled	4,935.87 F	*2,800.00 F
8	1		*LHS HEADLAMP LED MODULE (WCP)	Serviceable	909.59 F	*- F
9	1		*LHS HEADLAMP CONTROL UNIT (WCP)	Serviceable	933.02 F	*- F
10	1		*LHS HEADLAMP MODULE DAYTIME (WCP)	Serviceable	435.73 F	*- F
11	1		*FRONT BUMPER SIDE GRILLE LHS (WCP)	Serviceable	130.72 F	*- F
12	1		*FRONT BUMPER SIDE GRILLE CHROME LHS (WCP)	Cut	73.92 F	*22.00 F
13	1		*FRONT BUMPER DISTANCE SENSOR LHS	Serviceable	391.64 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (S\$) 13,803.10 **3,696.20**
+ Margin on L,N Items 0.00/15.00% (S\$) 0.00 **554.43**

Total Parts (S\$) 13,803.10 **4,250.63**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE	New	1,800.00	350.00
2	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT LHS FENDER	New	1,200.00	500.00
3	TO CHECK ELECTRICAL WIRINGS & LIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHT	New	150.00	30.00
4	CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS	New	300.00	100.00
5	TO REMOVE & REPLACE FRONT BUMPER DISTANCE SENSOR & TEST FUNCTION	New	150.00	30.00
Gross Labour Cost (S\$)			3,600.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >