



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 5283C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT	832.42	832.42
1	N/S HEADLAMP	CRACKED	721.30	721.30
1	N/S HEADLAMP RUBBER LID	MISSING	12.00	12.00
1	N/S SIGNAL LAMP	BROKEN	206.10	206.10
1	N/S SIDE REFLECTOR	BROKEN	139.05	139.05
1	N/S FRONT CORNER PANEL	BENT	398.41	398.41
1	N/S FRONT STEP GARNISH	SERVICEABLE	345.06	-
	LESS 25% DISCOUNT		-663.59	-577.32
			1,990.75	1,731.96
	<u>LABOUR</u>			
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.		250.00	220.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		640.00	500.00
	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.		30.00	20.00
			920.00	740.00
	GRAND TOTAL		2,910.75	2,471.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,950.00

Report Ref No. CS/AGI20007247/Ksf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.