

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31124

Date : 03-Apr-2020

Vehicle Insured : SJG 2586 H
Accident Date : 02-Apr-2020

PAGE : 1

Our Ref : 020178 (BUDGET) / SANDRA

JAREEN S/O A ANBU (MR)
Singapore

ESTIMATED COST OF REPAIR FOR MITSUBISHI FB70A (2835cc)(2006) YM5283C

1 pc front bumper	B 832.42 ✓
1 pc n/s headlamp	CM 721.30 ✓
1 pc n/s headlamp rubber lid	M 12.00 ✓
1 pc n/s signal lamp	B 206.10 ✓
1 pc n/s side reflector	B 139.05 ✓
1 pc n/s front corner panel	B 398.41 ✓
1 pc n/s front step garnish	S 345.06 X
	2,654.34
Less 25% :	-663.58
	1,990.76

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

220
250.00

To putty and respray on affected
portions.

500
640.00

To focus headlamps. To check front
wiring and lighting operation.

30.00

Total : S\$ 2,910.76

Singapore Dollars Two Thousand Nine Hundred and
Ten and Cents Seventy Six Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: