

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20007255/GSF3E2
Date: 22/07/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900067184
Claimant Vehicle No :	SLN1993L	Insured Vehicle No :	SLG811Y
Date of Loss:	13/07/2020	Nature of Claim:	TP
		Claim No:	5003365373SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1993L		
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Engine No:	P520434265
Reg. Date:	26/04/2017 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0146458
Colour:	Red	Odometer:	51350 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/07/2020	
Date Inspected:	14/07/2020 Inspected At:	14 AMK BLK B 569116
		Repairer : Assure Auto Assist Pte Ltd (tuas) (HQ)
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
8	1		*REAR END PANEL	Repair	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
10	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
11	1		*BOOTLID	Buckled	0.00 F	*- F
12	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LAMP LH	Broken	0.00 F	*- F
14	1		*BOOTLID LOCK	Bent	0.00 F	*- F
15	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >