

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III20007266/EDA3Q2

**Date:** 10/09/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0000193
<b>Claimant Vehicle No :</b>	SKG2010R	<b>Insured Vehicle No :</b>	SJM5159G
Date of Loss:	12/07/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0001300

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKG2010R</b>		
Make & Model:	BMW X1 SDRIVE18I, 1.5 LED NAV (A)	Engine No:	32845596B38B15A
Reg. Date:	30/05/2019 (Man. Year: 2019)	Chassis No:	WBAJG120703G77709
Colour:	Black	Odometer:	11526 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,496.80	1,696.50	800.30	32.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,084.00	583.00	21.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,163.80</b>	<b>3,780.50</b>	<b>1,383.30</b>	<b>26.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	361.47	264.64	96.83	26.79
<b>Nett Amount (S\$)</b>	<b>5,525.27</b>	<b>4,045.14</b>	<b>1,480.13</b>	<b>26.79</b>
<b>+ Loss of Use (3.0 x S\$80.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,287.14</b>		

### INSPECTION

Date of Assignment: 27/07/2020

Date Inspected: 27/07/2020 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

---

**Adjuster:** CHEN TSUE YEE**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2020)
<b>Parts:</b>	M1-SUV	BMW X1 SDRIVE18I 1.5 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKG2010R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*TAILPIPE TRIM BLACK CHROME	Not Necessary	112.20 FS	*- FS
3	1		*MOUNTING SMART OPENER	Not Necessary	45.55 FS	*- FS
4	1		*REAR TRIM UNDERCARRIDE PROTECTION (X L)	Cut	190.80 FS	*190.80 FS
5	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	142.65 FS	*- FS
6	1		*REAR BUMPER PANEL PRIMED	Crushed	903.40 FS	*903.40 FS
7	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Broken	265.65 FS	*265.65 FS
8	1		*REAR BUMPER TRIM BOTTOM (LINES)	Cut	232.45 FS	*232.45 FS
9	2		*ULTRASONIC SENSOR BLACK	Not Necessary	499.90 FS	*- FS
10	2		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	10.20 FS	*10.20 FS
11	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **2,496.80** **1,696.50**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE BUMPER REAR COVER AND ATTACHMENTS	New	1,275.00	850.00
2	TO SPRAY BUMPER REAR COVER	New	1,038.00	934.00
3	TO REMOVE OLD PDC ASSEMBLY REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>2,667.00</b>	<b>2,084.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**