

**ACCIDENT DAMAGED VEHICLE INSPECTION REPORT**

M/S : Nyanapragash S/O Arunasalam
C/O CCK CAR RENTAL
Blk 461 Pasir Ris Drive 4
#04-461 Singapore 510461

Date : 23 June 2020
Our Ref : TP/CCK/FBQ291M/6351

REFERENCE PARTICULARS

Date of Accident : 17 March 2020
Date of Inspection : 19 March 2020

Type of Inspection : Third Party Claim
Date of Re-Inspn : ~

VEHICLE PARTICULARS

Registration No : FBQ 291 M
Make : Yamaha
Model : NMAX155 ABS
Year : 2019

Engine No : G3H6E0013218
Chassis No : MH3SG431000010587
Odometer : 1424 km
Colour : White

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Front brake : Affected
Rear brake : Serviceable

General Body Work : Body frame affected
Steering : Affected
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

<u>Location</u>	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	: Timsun	110/70-13	3 mm
Rear	: Timsun	130/70-13	4 mm

GENERAL DESCRIPTION OF DAMAGES

The scooter sustained severe damage at the front & both side portion.

For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **\$8,100.00 nett** at lump sum basis. (Subject to GST if applicable).

Under normal circumstances, estimated period required for repairs : Twelve (12) working days.

Enclosed Twenty-Four (24) photographs depicting damage to the vehicle.

Inspection conducted at : Blk 5032 #01-307 Ang Mo Kio Industrial Park 2 Singapore 269535
Name Of Workshop : CCK CAR RENTAL

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS				ORIGINAL		REVISED	
A)	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	QUOTATION		QUOTATION	
1	Handle bar ✓	1	Bent	\$	280.00	\$	280.00 120
2	Handle bar holder @ \$34.00 X SVC	2	Bent	\$	64.00	\$	64.00 X
3	Handle bar bracket X SVC	1	Bent	\$	179.00	\$	179.00 X
4	Handle bar upper cover ✓	1	Torn	\$	168.00	\$	168.00 60
5	Handle bar cover X SVC	1	Torn	\$	35.00	\$	35.00 X
6	Handle bar lower cover X SVC	1	Deformed	\$	115.00	\$	115.00 X
7	Handle bar balancer LH X SVC	1 set	Grazed	\$	20.00	\$	20.00 X
8	Handle bar grip LH X SVC	1 set	Cut	\$	45.00	\$	45.00 X
9	View mirror LH ✓	1 set	Grazed/Bent	\$	160.00	\$	160.00 30
10	Brake lever L/R @ \$38.00 X SVC	2	Grazed/Bent	\$	76.00	\$	76.00 X
11	Front headlamp assy ✓	1	Cracked	\$	580.00	\$	580.00 160
12	Front headlamp stay X SVC	1	Bent	\$	590.00	\$	590.00 X
13	Front windshield ✓	1	Cracked	\$	197.00	\$	197.00 60
14	Front console panel cover X SVC	1	Cracked	\$	98.00	\$	98.00 X
15	Front console panel X SVC	1	Cracked	\$	159.00	\$	159.00 X
16	Front meter cover X SVC	1	Cracked	\$	85.00	\$	85.00 X
17	Front meter assy X SVC	1	Cracked	\$	680.00	\$	680.00 X
18	Front meter panel X SVC	1	Torn	\$	114.00	\$	114.00 X
19	Front leg shield assy X SVC	1	Cracked	\$	297.00	\$	297.00 X
20	Center body cover	1	Serviceable	\$	120.00		~
21	Front upper cowling L/R @ \$215.00 ✓	2	Cracked/Grazed	\$	430.00	\$	430.00 300
22	Front side panel L/R @ \$95.00 ✓	2	Grazed/Cracked	\$	190.00	\$	190.00 ✓
23	Front lower cowling L/R @ \$135.00 ✓	2	Grazed/Cracked	\$	270.00	\$	270.00 130
24	Side center cover L/R @ \$190.00 ✓	2	LH only (Grazed)	\$	380.00	\$	190.00 150
25	Front fender ✓	1	Cracked	\$	260.00	\$	260.00 95
26	Front wheel rim ✓	1	Warped/Dented	\$	590.00	\$	590.00 380
27	Front brake disc ✓	1	Warped	\$	245.00	\$	245.00 150
28	Front wheel rim rotor sensor X SVC	1	Serviceable	\$	115.00		~
29	Front wheel axle X SVC	1	Bent	\$	60.00	\$	60.00 X
30	Front fender inner ✓	1	Cracked	\$	105.00	\$	105.00 50
31	Lower under cover X SVC	1	Torn	\$	158.00	\$	158.00 X
32	Fork shaft assy L/R @ \$780.00 ✓	2	Bent	\$	1,560.00	\$	1,560.00 600
33	Lower fork bracket ✓	1	Bent	\$	740.00	\$	740.00 180
34	Front signal lamp L/R @ \$240.00	2	Cracked	\$	480.00	\$	480.00 50
35	Footrest board L/R @ \$280.00 X SVC	2	Grazed/Cracked	\$	560.00	\$	560.00 X
36	Footrest board rubber mat L/R @ \$48.00	2	Serviceable	\$	96.00		~
37	Rear side cover LH	1	Serviceable	\$	160.00		~
38	Rear side cowling LH	1	Serviceable	\$	195.00		~
				\$	10,656.00	\$	9,780.00 2705
				\$	1,065.60	\$	978.00
				\$	9,590.40	\$	8,802.00

2434.5

Balance B/F

\$ 9,590.40 \$ 8,802.00

B) S/NETT ITEM

39	Steering cone upper/lower bearing ✓	1 set	Necessary	\$ 68.00	\$ 68.00	✓
40	Front wheel rim bearing X SVC	1 set	Necessary	\$ 48.00	\$ 48.00	X
41	Front wheel rim seal X SVC	1 set	Necessary	\$ 12.00	\$ 12.00	X
42	Front wheel rim collar X SVC	1	Necessary	\$ 18.00	\$ 18.00	X
43	Duplicate ignition key X SVC	1	Bent	\$ 60.00	\$ 60.00	X
44	Front tyre (110/70-13) ✓	1	Cut	\$ 140.00	\$ 140.00	60
45	Front number plate sticker ✓	1	Cut/Necessary	\$ 12.00	\$ 12.00	✓
Parts Total :				\$ 9,948.40	\$ 9,160.00	140

C) LABOR CHARGES

46	Towing services.	\$ 50.00	\$ 50.00	✓
47	To straighten & re-align front body frame.	\$ 480.00	\$ 350.00	200
48	To check wiring, re-connection, lighting system & reset.	\$ 180.00	\$ 120.00	30
49	Replace, realign & adjust above damaged parts.			
	Remove & reinstall all body cover.	\$ 600.00	\$ 450.00	300
Labour Total :		\$ 1,310.00	\$ 970.00	580

Total Parts and Labour

\$ 11,258.40 \$ 10,130.00

FINAL LUMP SUM ADJUSTMENT

3154.5

\$ 8,100.00

-20%: 2500

5 days

REMARKS

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$8,100.00 nett** corresponding to replacement of parts and labour charges. We now revert for your decision on the above claim.

Yours faithfully
KTO Automobile Assessors



Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser











