



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 291M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	280.00	120.00
2	HANDLE BAR HOLDER @\$34.00	SERVICEABLE	64.00	-
1	HANDLE BAR BRACKET	SERVICEABLE	179.00	-
1	HANDLE BAR UPPER COVER	TORN	168.00	60.00
1	HANDLE BAR COVER	SERVICEABLE	35.00	-
1	HANDLE BAR LOWER COVER	SERVICEABLE	115.00	-
1	SET HANDLE BAR BALANCER LH	SERVICEABLE	20.00	-
1	SET HANDLE BAR GRIP LH	SERVICEABLE	45.00	-
1	SET VIEW MIRROR LH	GRAZED / BENT	160.00	30.00
2	BRAKE LEVER L/R @\$38.00	SERVICEABLE	76.00	-
1	FRONT HEADLAMP ASSY	CRACKED	580.00	160.00
1	FRONT HEADLAMP STAY	SERVICEABLE	590.00	-
1	FRONT WINDSHIELD	CRACKED	197.00	60.00
1	FRONT CONSOLE PANEL COVER	SERVICEABLE	98.00	-
1	FRONT CONSOLE PANEL	SERVICEABLE	159.00	-
1	FRONT METER COVER	SERVICEABLE	85.00	-
1	FRONT METER ASSY	SERVICEABLE	680.00	-
1	FRONT METER PANEL	SERVICEABLE	114.00	-
1	FRONT LEG SHIELD ASSY	SERVICEABLE	297.00	-
1	CENTER BODY COVER	SERVICEABLE	120.00	-
2	FRONT UPPER COWLING L/R @\$215.00	CRACKED / GRAZED	430.00	300.00
2	FRONT SIDE PANEL L/R @\$95.00	CRACKED / GRAZED	190.00	190.00
2	FRONT LOWER COWLING L/R @\$135.00	GRAZED / CRACKED	270.00	130.00
2	SIDE CENTER COVER L/R @\$190.00	N/S GRAZED	380.00	150.00
1	FRONT FENDER	CRACKED	260.00	95.00
1	FRONT WHEEL RIM	WARPED / DENTED	590.00	380.00
1	FRONT BRAKE DISC	WARPED	245.00	150.00
1	FRONT WHEEL RIM ROTOR SENSOR	SERVICEABLE	115.00	-
1	FRONT WHEEL AXLE	SERVICEABLE	60.00	-

Report Ref No. CS3/FWD20004287/Gtf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER INNER	CRACKED	105.00	50.00
1	LOWER UNDER COVER	SERVICEABLE	158.00	-
2	FORK SHAFT ASSY L/R @\$780.00	BENT	1,560.00	600.00
1	LOWER FORK BRACKET	BENT	740.00	180.00
2	FRONT SIGNAL LAMP L/R @\$240.00	N/S CRACKED / O/S	480.00	50.00
		SERVICEABLE		
2	FOOTREST BOARD L/R @\$280.00	SERVICEABLE	560.00	-
2	FOOTREST BOARD RUBBER MAT L/R @\$48.00	SERVICEABLE	96.00	-
1	REAR SIDE COVER LH	SERVICEABLE	160.00	-
1	REAR SIDE COWLING LH	SERVICEABLE	195.00	-
	LESS 10% DISCOUNT		-1,065.60	-270.50
			9,590.40	2,434.50
	<u>SPECIAL NETT ITEMS</u>			
1	SET STEERING CONE UPPER / LOWER BEARING (SN)	NECESSARY	68.00	68.00
1	FRONT WHEEL RIM BEARING (SN)	SERVICEABLE	48.00	-
1	FRONT WHEEL RIM SEAL (SN)	SERVICEABLE	12.00	-
1	FRONT WHEEL RIM COLLAR (SN)	SERVICEABLE	18.00	-
1	DUPLICATE IGNITION KEY (SN)	SERVICEABLE	60.00	-
1	FRONT TYRE (110/70-13) (SN)	CUT	140.00	60.00
1	FRONT NUMBER PLATE STICKER (SN)	CUT / NECESSARY	12.00	12.00
			358.00	140.00
	<u>LABOUR</u>			
	TOWING SERVICES.		50.00	50.00
	TO STRAIGHTEN & RE-ALIGN FRONT BODY FRAME.		480.00	200.00
	TO CHECK WIRING, RE-CONNECTION, LIGHTING SYSTEM & RESET.		180.00	30.00
	REPLACE, REALIGN & ADJUST ABOVE DAMAGED PARTS. REMOVE & REINSTALL ALL BODY COVER.		600.00	300.00
			1,310.00	580.00
GRAND TOTAL			11,258.40	3,154.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS3/FWD20004287/Gtf3e2-1



Report Ref No. CS3/FWD20004287/Gtf3e2-1

A handwritten signature in black ink, appearing to be 'XGQ'.

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

A handwritten signature in black ink, appearing to be 'ALWP'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.